Form 3160-5 (June 2015)

### UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

### BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals, 2010

5. Lease Serial No. NMLC029342E 6. If Indian, Allottee or Tribe Name

		APR 12	7013					
SUBMIT IN 1	RIPLICATE - Other inst	ructions on page 2  DISTRICTIL-AR	TESIA O.C.D	7. If Unit or CA/Agre	ement, Name and/or No.			
1. Type of Well	· · · · · · · · · · · · · · · · · · ·	DISTRICT		8. Well Name and No. THUNDER ROAL				
☑ Oil Well ☐ Gas Well ☐ Oth								
Name of Operator     COG OPERATING LLC		ABIGAIL ANDERSON cmandassociates.com	-	9. API Well No. 30-015-29910-0	)0-S1			
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	· · · · · ·	3b. Phone No. (include at Ph: 432-580-7161	rea code)	10. Field and Pool or GRAYBURG	Exploratory Area			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description,	)	, <u></u>	11. County or Parish,	State			
Sec 20 T17S R30E SWNE 23	10FNL 2310FEL	· ,		EDDY COUNT	Y, NM			
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICÀTE NATI	URE OF NOT	TICE, REPORT, OR OT	HER DATA			
TYPE OF SUBMISSION		T	YPE OF ACTI	ION ·				
Notice of Intent	☐ Acidize	☐ Deepen	□ P	roduction (Start/Resume)	■ Water Shut-Off			
☑ Notice of Intent	☐ Alter Casing	☐ Hydraulic Frac	cturing 🗖 R	eclamation	■ Well Integrity			
☐ Subsequent Report	, <del>–</del>		tion 🗖 R	ecomplete	Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abar	idon 🔲 T	emporarily Abandon				
	☐ Convert to Injection	Plug Back	□ W	Vater Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  1. Set 5 1/2" CIBP @ 4267'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 4267-4067'.  2. Spot 25 sx cmt @ 2850-2650'. (San Andres)  3. Spot 35 sx cmt @ 1200-900'. WOC & Tag (Yates & B/Salt)  4. Spot 60 sx cmt @ 576'-Surface. (T/Salt & Shoe)  5. Cut off well head, verify cmt to surface, weld on Below Ground Dry Hole Marker.  SEE ATTACHED FOR CONDITIONS OF APPROVAL								
14. I hereby certify that the foregoing is	true and correct.	role mark		بدي احط				
Con	Electronic Submission #	PERATING LLC, sent t essing by PRISCILLA P	o the Carlsbac	d				
Signature (Electronic S	Submission)	. Date (	03/28/2019					
	THIS SPACE FO	OR FEDERAL OR S	TATE OFFI	CE USE				
Approved By	a. amo_	Title	SALT	<u>-</u>	4-6-19 Date			
Conditions of approval, if any, are attache certify that the applicant holds legal or equivich would entitle the applicant to conductive to conductive the applicant to conduct the applicant to conductive the applicant to condu	uitable title to those rights in the operations thereon.	e subject lease Office	Ct0		·			
The 18 U.S.C. Section 1001 and Title 43				ly to make to any department of	r agency of the United			

## Thurder Road Federal #1 30-015-29910

Spud - 12/4/97

GL Elev.: 3469'

KB -

12/4" hole

8 5/8" J-55 24# @ 420', 350 sx class C cmt, circ 100 sx to pit

Tubi										
Tubris Desiration   Production Tubina				58: Desth (fi-f3) 4,786.1		501 Date 10/1/2014		F.# Date	Put Date	
Production reding										
A.	nam Dei	OB (Mn)	(D) (M)	Va (15%)	Grade	Toc	1en(1)	Top (1:K5)	59M (CKS)	
131	TUBING	2 7/8	2,44	6.50	J-55		4,109.6 9	. 10.0	4,119.7	
	MARKER SUB	2 7/8	2.44	6.50	J-55		2,00	4;119:7	4,121.7	
2	TUBING	2 7/8	2,44	6.50	J-55		52.88	4,121.7	4,184.6	
	TUBING ANCHOR	5.1/2	2.44	15.00	K-55		3.00	4,184.6	4,187.6	
19	TUBING	2 7/6	2.44	6.50	J-55		597.40	4:187:6	4,785.0	
	SEAT NIPPLE	2 7/8	2.25	6.50	J-55		1.10	4,785.0	4,786.1	

Rod String .		Se: D	Se: Dapto (5/(5)		s:≘ /2014	9/29/2014			
Ro	d Components								
.15 1	nem Descoption	55 (4%) 1 1/4	VAND D	Grape	Strace: Det 14	רב'וזו	Length (5) 26.00		57n (3KB) -4,742.0
-12 1	dem Description	00 (tr) 1	\$75 (AD-75)	Grade	Straper Dasor	:A:27	_ength (1); 2.00	Top (11K5) -4.742.0	
1	Her Description	90 pt	Vitalia ti	G-abs	Strate: Destr	יכוקו	Langth (ft) 4,00	Top (\$25) -4,740.0	
-15 1	nem Description	60 (m) 1	एस एक है।	Grade	Strace: Eleicr	יכ זמו	Sength (f); 8,90	Tap (12:45) -4,736.0	5vm (tx5) -4,730.0
-15	Her Description	og (स) 1	Vin (10 ft)	Grade	Strate: Dest	וביצקו	Length (f): 6.00	Top(fA5) . -4,730.0	
-:: 54	nen Descri <b>o</b> ton	90 (kn) 1	VYD (Fo fil	Grade	Strate: Destr	1 <b>00</b> 07	Lergin (8) 1.359.00	Top (fix5):	5xn (105) -3,374,0
12 8	нет Вестраоп	50 (fr) 7/8	Vitteti	G*939	Styager Destr	ist on	цепруп (п) 3.200.00	Top (0K5): -3,374.0	5m (10.5) -174.0
8	Hem Description	30 (M) 1 1/2	Vivi (re fi)	Grade	Strater Deter	egi ten	150.00	Top (6KS)	55m (1+3) -24.0
1	Secretar	95 ( t) 7/8	११त (१२त)	Grape	Strater Desp	יכוסו	_ength (8) 4.00	Top (70/3) -24.0	51n (5-39) -20.0
.35 1	ten Description	55 (M) 2	17.5 (\$5.5)	G1909	50/209: E 810:	רכיזכו	Length (ft) 20,00	Tac (fi/C5) - -20.0	925 (EKS) 0.0

Marker jt 4121'

Paddock

4317' - 4713' (20 shots) -

7 7/8

PBTD-4850'

1st stage: Cmtd w/400 sx 50/50 POZ, circ 110 sx to surf. 2nd stage: Cmtd w/600 sx H/L and 300 sx 50/50 POZ, circ 150 sx to surf. 5 1/2" 17 # csg @ 4850'—

TD 4865

11/2 · 1/ # CSQ @ 4000

32.821003

-103.9931107

T/Self 360 B/Self 780

(ESt)

Yetes 930 78 1145

7R 1145 Ou 1815

68 2140

SA 2510

B1. 3900

Lease & Well #

Thunder Road Federal #1

30-015-29910

Spud - 12/4/97

GL Elev.: 3469'

8 5/8" J-55 24# @ 420', 350 sx class C cmt, circ 100 sx to pit

4. Spot 60 sx cmt @ 576' to surface. (T/Salt & Shoe)

3. Spot 35 sx cmt @ 1200-900'. WOC & Tag (Yates & B/Salt)

2. Spot 25 sx cmt @ 2850-2650'. (San Andres)

1. Set 5 1/2" CIBP @ 4267'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 4267-4067 Paddock

4317' - 4713' (20 shots)

1st stage: Cmtd w/400 sx 50/50 POZ, circ 110 sx to surf. 2nd stage: Cmtd w/600 sx H/L and 300 sx 50/50 POZ, circ 150 sx to surf. 5 1/2" 17 # csg @ 4850',

PBTD-4850'

Marker jt 4121'

KB -

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted