

Submit 1 Copy To Appropriate District
Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-23728
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Permian Water Solutions LLC		6. State Oil & Gas Lease No. VA-3055-0001
3. Address of Operator 600 Travis Street, Suite 4700 Houston TX 77002		7. Lease Name or Unit Agreement Name Dorstate SWD
4. Well Location Unit Letter _____ H _____ : 1980 _____ feet from the _____ N _____ line and _____ 660 _____ feet from the _____ E _____ line Section 27 Township 25S Range 28E NMPM County: Eddy		8. Well Number 001
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL: 2968		9. OGRID Number 373626
		10. Pool name or Wildcat SWD; Bone Spring

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: Step Rate Test <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Step Rate Test Procedure

1. Shut well in.
2. MIRU pump truck.
3. Test iron.
4. Start pumping step rate.
5. Gradually increase and record rates and pressures every 100psi.

Notes: Make sure iron is tested and stamped, make sure chart recorder is calibrated.

RECEIVED

MAY 01 2019

DISTRICT II-ARTESIA O.C.D.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brian Wood

TITLE Consultant

DATE

4/30/2019

Type or print name Brian Wood E-mail address: brian@permitswest.com PHONE: 505-466-8120

For State Use Only

Accepted for record - NMOCID

APPROVED BY:

TITLE

DATE

5-1-19

Conditions of Approval (if any):

Permitted pressure 1040 psi Carb Production 1-1-19