Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	Lease Serial No.
٠	NMNM114979

Do not use this abandoned well	. Use form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name	
SUBMIT IN T	RIPLICATE - Other instr	uctions on page 2	7. If Unit or CA/Ag	reement, Name and/or No.	
1. Type of Well			8. Well Name and N MESA VERDE		
Oil Well Gas Well Other 2. Name of Operator		AEL ANIE VAIL CON		300 3	
MESQUITE SWD, INC.	Contact: N E-Mail: mjp1692@g	MELANIE WILSON mail.com	9. API Well No. 30-015-44676		
3a. Address PO BOX 1479 CARLSBAD, NM 88221		3b. Phone No. (include area code Ph: 575-914-1461	e) 10. Field and Pool of SWD;DEVON	r Exploratory Area IAN	
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Description)		11. County or Parisl	n, State	
Sec 13 T24S R31E Mer NMP S	SESW 1030FSL 2635FW	L	EDDY COUN	TY, NM	
12. CHECK THE AP	PROPRIATE BOX(ES)	ΓΟ INDICATE NATURE (DF NOTICE, REPORT, OR OT	THER DATA	
TYPE OF SUBMISSION		ТҮРЕ С	OF ACTION	<u> </u>	
D Notice of Interes	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☑ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon		
	☐ Convert to Injection	□ Plug Back	■ Water Disposal		
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved testing has been completed. Final Aba determined that the site is ready for fin	ration: Clearly state all pertinen ally or recomplete horizontally, go will be performed or provide to operations. If the operation resundonment Notices must be file all inspection.	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red d only after all requirements, inclu	nured and true vertical depths of all perior. A. Required subsequent reports must loompletion in a new interval, a Form 3 ding reclamation, have been completed.	tinent markers and zones. be filed within 30 days 160-4 must be filed once	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved of testing has been completed. Final Aba	ration: Clearly state all pertinen ally or recomplete horizontally, go will be performed or provide to operations. If the operation resundonment Notices must be file all inspection.	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red d only after all requirements, inclu	nured and true vertical depths of all period. Required subsequent reports must be completion in a new interval, a Form 3 ding reclamation, have been completed 1545 psi.	tinent markers and zones. be filed within 30 days 160-4 must be filed once	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved ctesting has been completed. Final Abadetermined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres	ration: Clearly state all pertinen ally or recomplete horizontally, go will be performed or provide to operations. If the operation resundonment Notices must be file all inspection.	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red d only after all requirements, inclu	aured and true vertical depths of all periods. Required subsequent reports must be completion in a new interval, a Form 3 ding reclamation, have been completed 54545 psi.	tinent markers and zones. se filed within 30 days 160-4 must be filed once d and the operator has	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved ctesting has been completed. Final Abadetermined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres	ration: Clearly state all pertinen ally or recomplete horizontally, go will be performed or provide to operations. If the operation resundonment Notices must be file all inspection.	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red d only after all requirements, inclu	ured and true vertical depths of all per A. Required subsequent reports must be completion in a new interval, a Form 3 ding reclamation, have been completed 54545 psi.	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved ctesting has been completed. Final Abadetermined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres	ration: Clearly state all pertinently or recomplete horizontally, a will be performed or provide toperations. If the operation resundonment Notices must be filenal inspection. Source test to 540 psi for 34 ps	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red d only after all requirements, inclu	pared and true vertical depths of all per A. Required subsequent reports must be completion in a new interval, a Form 3 ding reclamation, have been completed 1545 psi. DISTRICTION DISTR	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved ctesting has been completed. Final Abadetermined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres MIT chart attached.	ration: Clearly state all pertinently or recomplete horizontally, a will be performed or provide toperations. If the operation resundonment Notices must be file hal inspection. Source test to 540 psi for 34 p	give subsurface locations and meas he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, including the minutes. Start 540 psi, end minutes. Start 540 psi, end 69433 verified by the BLM WillE SWD, INC., sent to the Country of the BLM Will SWD, INC., sent to the Country of the BLM Will SWD, INC., sent to the BLM Will SWD, sent to the BLM	pared and true vertical depths of all per A. Required subsequent reports must be completion in a new interval, a Form 3 ding reclamation, have been completed 1545 psi. DISTRICTION DISTR	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved of testing has been completed. Final Abadetermined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres MIT chart attached.	ration: Clearly state all pertinently or recomplete horizontally, and will be performed or provide toperations. If the operation resundonment Notices must be file hal inspection. Source test to 540 psi for 34	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red only after all requirements, including a minutes. Start 540 psi, end for the Swd, INC., sent to the Cartille REGU	A. Required subsequent reports must be completed in a new interval, a Form 3 ding reclamation, have been completed in 545 psi. DISTRICTION DISTRICTION Ell Information System arrishad	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved of testing has been completed. Final Abadetermined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres MIT chart attached.	ration: Clearly state all pertinently or recomplete horizontally, a will be performed or provide toperations. If the operation restandonment Notices must be file hal inspection. Source test to 540 psi for 34 for MESQUE	give subsurface locations and meas he Bond No. on file with BLM/BI alts in a multiple completion or red only after all requirements, including a minutes. Start 540 psi, end for the SWD, INC., sent to the Completion of the Completion of the Completion of the SWD, INC., sent to the SWD, INC., sent to the SWD, INC., sent to the Completion of the SWD, INC., sent to the SWD, INC., sent	A. Required subsequent reports must loompletion in a new interval, a Form 3 iding reclamation, have been completed if 545 psi. DISTRICTION DISTRICTION System arisbad LATORY ANALYST	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	
Attach the Bond under which the work following completion of the involved of testing has been completed. Final Aba determined that the site is ready for fin 06/05/19 - Ran MIT Test. Pres MIT chart attached. 14. I hereby certify that the foregoing is to Name (Printed/Typed) MELANIE V. Signature (Electronic Su	ration: Clearly state all pertinently or recomplete horizontally, a will be performed or provide toperations. If the operation restandonment Notices must be file hal inspection. Source test to 540 psi for 34 for MESQUE	give subsurface locations and meas he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, including a minutes. Start 540 psi, end for a minutes. Start 540 psi, end for a minutes. Start 540 psi, end for a minutes. Title REGU Date 06/17/2	A. Required subsequent reports must loompletion in a new interval, a Form 3 iding reclamation, have been completed if 545 psi. DISTRICTION DISTRICTION System arisbad LATORY ANALYST	tinent markers and zones. be filed within 30 days 160-4 must be filed once d and the operator has	