| Submit 1 Copy To Appropriate District | State of New Mexic | 0 | Form C-103 |
|--|--|---|---|
| Office Encourse Minards and Network Decourses | | | Revised August 1, 2011 |
| District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 | | W | ELL API NO. |
| District II - (575) 748-1283 OIL CONSERVATION DIVISION | | 20 | -015-35558 |
| 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 | 1 5. 1 hat bit, 7 hitosia, 140 66210 | | Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 | D Rio Brazos Rd Aztec NM 87410 | | STATE 🛛 FEE 🗌 |
| <u>District IV</u> $-$ (505) 476-3460 | Santa Fe, NM 8750 | 6. | State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | |
| | S AND REPORTS ON WELLS | 7. | Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSAL | | | |
| DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.) | ION FOR PERMIT" (FORM C-101) FOR S | | lack Lake 7 SWD (Kimber State) |
| 1. Type of Well: Oil Well 🔲 Ga | s Well 🖾 Other | | Well Number |
| 2. Name of Operator | | 00 | OGRID Number |
| OWL SWD Operating LLC. | | | 8339 |
| 3. Address of Operator | | | . Pool name or Wildcat |
| 8214 Westchester Drive Suite 850 Dal | las, Texas 75255 | | 6100) SWD, Delaware |
| 4. Well Location | | | |
| Unit Letter E: 660 feet from theNorth line and1980 feet from theWest line | | | |
| Section 7 | Township 25S Ran | | NMPM Eddy County |
| | 1. Elevation (Show whether DR, RK | | |
| | 3067' GL | D, RI, OR, etc.) | |
| | | | |
| 12 Check Am | ropriate Box to Indicate Natu | re of Notice Rei | port or Other Data |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | |
| NOTICE OF INTE | INTION TO: | SUBSE | QUENT REPORT OF: |
| PERFORM REMEDIAL WORK 🔲 🛛 F | LUG AND ABANDON | EMEDIAL WORK | □ ALTERING CASING □ |
| TEMPORARILY ABANDON | HANGE PLANS 🔲 CO | MMENCE DRILLIN | IG OPNS. 🔲 P AND A 🛛 🛛 |
| PULL OR ALTER CASING | NULTIPLE COMPL 🔲 CA | SING/CEMENT JC | B T |
| DOWNHOLE COMMINGLE | | | |
| OTHER: | | HER: | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date | | | |
| 15. Describe brodosed of comblete | a operations. I Clearly state all pern | nent details, and give | e pertinent dates including estimated date |
| of starting any proposed work) | . SEE RULE 19.15.7.14 NMAC. F | or Multiple Comple | tions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom | . SEE RULE 19.15.7.14 NMAC. F | or Multiple Comple | tions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom | . SEE RULE 19.15.7.14 NMAC. F pletion. | or Multiple Comple | tions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. | or Multiple Comple | tions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 2001 | or Multiple Comple Bbl. Salt Gel Mud. | tions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipmo 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do | etions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta | tions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipm 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta | etions: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipm 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta | etions: Attach wellbore diagram of |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipm 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 1 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez | etions: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ e 100 sacks Class C 100'- Surface in 7" x |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 1 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C l. back. RU 1" hose and RI ₁ 13 3/8" cas | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge | etions: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ e 100 sacks Class C 100'- Surface in 7" x |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C b. back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge | witions: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ e 100 sacks Class C 100'- Surface in 7" x d @50'. Pumped 3 sxs cement and 4" marker joint on plate that is sticking 4' |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C b. back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge | witions: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ e 100 sacks Class C 100'- Surface in 7" x d @50'. Pumped 3 sxs cement and 4" marker joint on plate that is sticking 4' |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C b. back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge | witions: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ e 100 sacks Class C 100'- Surface in 7" x d @50'. Pumped 3 sxs cement and 4" marker joint on plate that is sticking 4' 2' below ground level. |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C b. back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge | withons: Attach wellbore diagram of own for the day. g Plug @ 2243'. L/D 76 Joints. EOT @ e 100 sacks Class C 100'- Surface in 7" x d @50'. Pumped 3 sxs cement and 4" marker joint on plate that is sticking 4' 2' below ground level. |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C b. back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded achors were cutoff? | Approved for plugging of well hare only. Liability under bond is retained pending receipt (C 103 (Surfacement Report of Well Plugging) |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge | Approved for plugging of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C b. back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded achors were cutoff? | Approved for plugging of well hare only. Liability under bond is retained pending receipt (C 103 (Surfacement Report of Well Plugging) |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An | or Multiple Comple Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded achors were cutoff? | Approved for plugging of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded achors were cutoff (| Approved for plugging of well hare only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found it OCD Web Page under Forms, www.emard.s |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded achors were cutoff (| Approved for plugging of well hare only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found it OCD Web Page under Forms, www.emard.s |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: RU 6/17/2019 | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded achors were cutoff (| Approved for plugging of well hare only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found it OCD Web Page under Forms, www.emard.s |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: RU 6/17/2019 | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded inchors were cutoff? | Approved for plugging of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emard.steenm.us/ocd. |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 7 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: RU 6/17/2019 I hereby certify that the information above | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: ve is true and complete to the best o | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge to n plate. Welded hochors were cutoff? 6/21/2019 f my knowledge an Manager, EWS Co | Approved for plugance of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.stre.nm.us/ocd. |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 7 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: RU 6/17/2019 I hereby certify that the information above SIGNATURE <u>MacMacMacMacMacMacMacMacMacMacMacMacMacM</u> | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: ve is true and complete to the best o | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge to n plate. Welded hochors were cutoff? 6/21/2019 f my knowledge an Manager, EWS Co | Approved for plugance of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.stre.nm.us/ocd. |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 7 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish r 93'. Perforate @ 581'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: RU 6/17/2019 I hereby certify that the information above | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI 13 3/8" cas ag 5' below ground level and welded equired information welded on it. An Rig Release Date: ve is true and complete to the best o | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge to n plate. Welded hochors were cutoff? 6/21/2019 f my knowledge an Manager, EWS Co | Approved for plugging of well here only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found it OCD Web Page under Forms, www.emard.steenm.us/ocd. d belief. |
| of starting any proposed work) proposed completion or recom 6-17-19 MIRU WSU & P & A Equipme 6-18-19 RIH Tag CIBP @ 4522' With 7 6-19-19 L/D 79 Joints, EOT @ 2033'. 6-20-19 Perforate @ 2450'. Establish rate. 6-21-19 L:/D 2 Joints. Packer @ 31'. I 9-5/8" Annulus and leave 7" Casing ful 6-30-19 Determined cement had fallen circulated back to surface. Cut off casin above ground level. Marker joint has re Spud Date: RU 6/17/2019 I hereby certify that the information above SIGNATURE <u>MacMacMacMacMacMacMacMacMacMacMacMacMacM</u> | . SEE RULE 19.15.7.14 NMAC. F pletion. ent. Notify NMOCD of R/U. Fubing. L/D 1 Joint. Circulate 200 R/U Wireline. Misfire. Line Strand ate. Squeeze 45 sacks Class C 2450 Squeeze 45 sacks Class C 581'-481' Perforate @ 100'. Establish rate & C back. RU 1" hose and RI,13 3/8" cas ag 5' below ground level and welded and welded on it. An required information welded on it. An Rig Release Date: ve is true and complete to the best of TITLE Operations and address: rick@ewsconsulting.co | or Multiple Complete Bbl. Salt Gel Mud. ed @ 885'. Shut do '-2300'. WOC. Ta Circulation. Squeez ing annulus. Tagge on plate. Welded hechors were cutoff? 6/21/2019 f my knowledge an Manager, EWS Co om PHONE: 432-6 | Approved for plugance of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.stre.nm.us/ocd. |