Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	ÓN GOMADAN ANOMANA		30-015-31041	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE	FED
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, NIVI 87303		6. State Oil & Gas Lease No.	
87505		77 T N T T T T T T T T T T T T T T T T T		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreemen	it Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		M Dodd B Deep Federal		
1. Type of Well: Oil Well	Gas Well 🛛 Other SWD		8. Well Number 2	
2. Name of Operator		9. OGRID Number		
COG Operating LLC 3. Address of Operator			229137 10. Pool name or Wildcat	
600 W Illionis Ave, Midland, TX 79701		Grayburg-Jackson-SR-QN-GB-SA		
4. Well Location			Grayoung vacasion on QIV GB SI	-
Unit Letter H	: 1980 feet from the Nort	h line and 1	295 feet from the East	line
Section 14	Township 17S			County
· · · · · · · · · · · · · · · · · · ·	11. Elevation (Show whether DR	, RKB, RT, GR, etc.)	anger operation of the second	
	3625	•		
12 Charle	Ammonwista Day to Indicate N	Isanin - CNI-41 I		
12. Check	Appropriate Box to Indicate N	ature of Notice, I	Report or Other Data	
	NTENTION TO:		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK				SING 🗌
TEMPORARILY ABANDON DULL OR ALTER CASING				· 📙 .
DOWNHOLE COMMINGLE	-	CASING/CEMENT	JOB	
CLOSED-LOOP SYSTEM			-	
OTHER: HIT (Possible Packer		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
The original plan was to P&A this well due to a failed MIT. The decision has been made to repair the well and return to an active SWD. We have already run the blanking plug to the packer and determined we have a tubing leak. We will replace any failed jts of IPC tbg.				
we have already full the blanking p	rug to the packer and determined we	nave a lubing leak.	we will replace any falled jts of 1-	C tog.
Please see the attached Procedure a	nd WBD.		NM OIL CONSER	VATION
			ARTESIA DISTR	.ICT
			SEP 20 20	119
	•			
	•		RECEIVE	D
		•		
				
Spud Date:	Rig Release Da	nte:		,
			·	ř
		 -		
I hereby certify that the information	above is true and complete to the b	est of my knowledge	and belief.	
A / N.	<i>)</i>			
SIGNATURE Jana 4	TITLE_	Permit Specialist II	DATE9/18/2019	
The second of th	O			
Type or print name Dana King For State Use Only	E-mail address	: _dking@concho.c	om PHONE: 432-818-	-2267
			N .I	
APPROVED BY: Da Amel	TITLE COM	pliance	Office DATE 9-25	-15
Conditions of Approval (if any):		•		

General Information

Well Name: M Dodd B Deep Federal #2

API#: 30-015-31041 Issue: Failed MIT

Lat/Long: 32.8364449,-104.041069

Procedure Prepared By: Thomas Rebenack

Date Prepared: 9/18/2019

Procedure

- I have spoken to Dan at the OCD. We are not required to contact him if we are only pulling tubing. We must contact him only if we plan on pulling or moving the packer.
- If we have a HIT, then ND the WH and NU BOP
 - TOOH w/ tubing and lay it down on pipe racks to thoroughly inspect it for corrosion or abnormalities
 - o Replace any bad joints
 - We have some spare IPC tubing in Concho's inventory. Reach out to procurement
 - o Run back w/ the same tubing design and setting depths. Hydrotest back in to 5,000 psi
- If we have a packer leak, then pull the blanking plug, shut in the casing and pump 60 bbls of 10# brine down the tbg
 - o Please call Engineer with the SITP so we can discuss the kill mud weight we need to order
 - We will need a total of 250 bbls of mud
 - o 60 bbls of mud will need to be bull headed down the tubing
 - 150 bbls of mud will need to be bull headed down the csg
 - o 40 bbls extra
 - Once the well is dead TOOH w/ the tbg and packer
 - Please have Kenco take the packer in for repair
 - Run back w/ the same tubing design and setting depths. Hydrotest back in to 5,000 psi
 - o Get off O/O tool and reverse circulate annulus w/ approximately 150 bbls of packer fluid
 - Latch onto injection packer
 - Pressure up on the tog to rupture the pump out plug
- ND BOP, NU WH
- Contact NMOCD to witness the MIT
- Clean location and turn over to operations

Wellbore Diagram on page 2

