

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural ResourcesOIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised May 08, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30.015.01763
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator BP America Production Company		6. State Oil & Gas Lease No. 647
3. Address of Operator P.O. Box 1089 Emice NM 88231		7. Lease Name or Unit Agreement Name: Empire Abo Unit "G"
4. Well Location Unit Letter F : 1/4 feet from the NW line and 1/4 feet from the SE line Section 34 Township 17S Range 28E NMPM County ddy		8. Well No. 35
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3672' DR		9. OGRID Number 000778
10. Pool name or Wildcat Empire Abo		

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including casing completion date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6380' PED: 6190' PERFS: 5788-5968'

08.20.04: MUDFU. NUBH. NUBOP. RWL RTH w/guide ring and tag @ 6194'. POH. RTH w/cmt bailer and dump 35' cmt on top of plug. RTH w/bit & scraper @ 6116' 2-3/8" tbg. Test tbg in hole to 500#.

08.23.04: Swab 115 BW to bring FL down to 5200'.

08.24.04: POH. RWL. RTH w/logging tools. Select perfs. POH.

08.25.04: RTH w/perf guns & perf 5788-5968', 52 holes, w/2 JSPF. RWL. RTH w/plr, SW, & tbg to 5685'.

08.26.04: Set plr @ 5685'. RT acid trucks & acidize well w/4000 gals 15% HCL Nitrofuric acid.

08.30.04: PU swab. Tag FL @ 3000'.

08.31.04: RT & pump 20 bbls produced wtr down tbg. Unset plr. RTH w/6 standing tbg. RO frac balls.

POH w/workstring. RTH w/prod easy. NUBOP. Set TAC. NUBH. RTP. 09.27.04: well pup'd 1

BO,

57 MCF, 124 BW. 2 3/8" tbg set @ 6003'. SW @ 6018'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Scheduler DATE 12.06.04Type or print name Kellie D. MurrishTelephone No. 505.394.1649

(This space for State use)

FOR RECORDS ONLY

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any:

CRG: CF
 XC: KRM/FILES
 12.11.04

DEC 08 2004