# **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF L'AND MANAGEMENT

Carisbad	Field	FOR APPROVED
OCD	A	Expires: January 31, 20
	L 54 He 85 0 3 8	GHANO.

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMNM118707  6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2		7. If Unit or CA/Agre	eement, Name and/or No.
Type of Well     ☐ Gas Well ☐ Oth	ner		**************************************		8. Well Name and No DELAWARE RAI	NCH 12 B2MD FED COM 2
Name of Operator			9. API Well No. 30-015-43471-00-X1			
3a. Address P O BOX 5270 HOBBS, NM 88241		3b. Phone No. (include area code) Ph: 575-393-5905			10. Field and Pool or Exploratory Area RED BLUFF	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 13 T26S R28E NWNW 230FNL 180FWL				EDDY COUNT	Y, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OT	HER DATA
TYPE OF SUBMISSION			TYPE OF ACTION			
☑ Notice of Intent	☐ Acidize	□ Dee	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off
<del></del>	☐ Alter Casing	□ Нус	raulic Fracturing	☐ Reclam	ation	☐ Well Integrity
☐ Subsequent Report	□ Casing Repair	_	Construction	☐ Recomp		
☐ Final Abandonment Notice	Change Plans		g and Abandon		arily Abandon	PD PD
13. Describe Proposed or Completed Op	Convert to Injection	Plug		☐ Water I		
testing has been completed. Final Al determined that the site is ready for f Mewbourne Oil Company requal (1) Change well name to Delay (2) Change target zone to Wol (2) Change SHL to 545' FNL (3) Change casing (3) Change casing (4) Change target zone to Wol (4) Change casing (5) Change casing (6) Change target zone to Wol (6) Change casing (6) Change target zone to Wol (6) Change target zone target zone target zone target zone target zone zone zone zone zone zone zone zone	inal inspection.  uests approval to make the  ware Ranch 13/24 W1DM  fcamp & pool to Purple Si  120' FWL, Sec 13, T26S  esign as detailed in attact	ne following of Fed Com #2 age Wolfcam I, R28E /7 hed drilling pr	nanges to the app	proved APE		RECENED :
See attachments for C-102, d Please contact Andy Taylor w	rilling program & direction ith any questions.	ial plan			nierro	2010
	ce a Hachel COI	4. 2s c	5-19-19	C	SEE ATTA	IICTII-ARTESIAO.C.D. CHED FOR OF APPROVAL
14. Whereby certify ∫hat the foregoing is	Electronic Submission #	RNE OIL COM	PAÑY, sent to the	e Carlsbad	•	·
Name (Printed/Typed) ANDY TA			Title ENGINE			
Signature (Electronic Submission)		Date 06/13/2	019			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE	
Approved By Confl	1 last		Title #	4-1	{M	Bate 126/2014
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conditions.	uitable title to those rights in the		Office Off	O .		, 
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to m	ake to any department o	or agency of the United

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

NO 102 PIATI RIP10-29-10

# PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: Mewbourne Oil Company

**LEASE NO.: | NMNM118707** 

WELL NAME & NO.: DelawareRanch 13/24 W1DM Fed Com 1H

SURFACE HOLE FOOTAGE: | 545'/N & 120'/W BOTTOM HOLE FOOTAGE | 330'/S & 990'/E

LOCATION: | Section 13, T.26 S., R.28 E., NMPM

**COUNTY:** | Eddy County, New Mexico

COA

All previous COAs still apply expect the following:

H2S	Yes	€ No	
Potash	• None	Secretary	← R-111-P
Cave/Karst Potential	C Low	Medium	C High
Variance	None	Flex Hose	Other
Wellhead	Conventional	• Multibowl	© Both
Other		Capitan Reef	WIPP

# A. Hydrogen Sulfide

Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the Hydrogen Sulfide area shall meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, provide measured values and formations to the BLM.

#### **B. CASING**

- 1. The 13-3/8 inch surface casing shall be set at approximately 250 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface.
  - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
  - b. Wait on cement (WOC) time for a primary cement job will be a minimum of **8** hours or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
  - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours

- after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
  - Cement to surface. If cement does not circulate see B.1.a, c-d above. Additional cement maybe required. Excess calculates to 20%.

Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.

- ❖ In Medium Cave/Karst Areas if cement does not circulate to surface on the first two casing strings, the cement on the 3rd casing string must come to surface.
- 3. The minimum required fill of cement behind the 7 inch production casing is:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

- a. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.
- b. Second stage above DV tool:Cement should tie-back at least 200 feet into previous casing string. Operator shall provide method of verification.
- 4. The minimum required fill of cement behind the 4-1/2 inch production liner is:
  - Cement should tie-back 100' into the previous casing. Operator shall provide method of verification.

### C. PRESSURE CONTROL

- 1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 5000 (5M) psi.

## ZS 061919