

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-103) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-10128
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒ Injection Well		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator United Oil & Minerals Limited Partnership		6. State Oil & Gas Lease No. E-9262
3. Address of Operator 1001 Westbank Dr., Austin, TX 78746		7. Lease Name or Unit Agreement Name North Benson Queen Unit
4. Well Location Unit Letter L : 1650 feet from the South line and 660 feet from the West line Section 27 Township 18S Range 30E NMPM Eddy County		8. Well Number 18
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3484 KB		9. OGRID Number 5300
		10. Pool name or Wildcat Queen - Grayburg

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Contact OCD 24 hours prior to any work being done
- Fill hole, including between plugs, with salt gel mud consisting of 10# brine with 25# of gel per barrel
- Plugs to be set at the following depths:
 - i. Set 100' (25 sx minimum) plug from 2,750-2,650' and tag
 - ii. Set 100' (25 sx minimum) plug from 1,570-1,470' and tag *25 sx @ 1570' - tag*
 - iii. Set 100' (25 sx minimum) plug from 500-400' and tag *Perf. csg. @ 500' - Place 100' of cmt inside & outside of csg. 400' - 500' - tag.*
 - iv. ~~Set 60' surface plug from 60' to surface~~
- Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists behind pipe. TOC in this well is 550'.
- Install dry hole marker as per Rule 202.B.2 *Perf. csg. @ 60' - Place 60' of cmt. inside & outside of csg. 0' - 60' - WOC 24 HRS - tag*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Curless Patton TITLE Regulatory Coordinator DATE _____

Type or print name Mary Curless Patton E-mail address: mpatton@uominc.com Telephone No. (512) 328-8184

(This space for State use)

APPROVED BY [Signature] TITLE Wild Dog ID DATE APPROVED JUL 24 2003

Conditions of approval, if any:

OPERATOR: United Oil & Minerals			API#	30-015-10128	
WELL: North Benson Queen Unit # 18			LOCATION:	L-27-18-30	
SURFACE CSG-HOLE SIZE"	CSG. SIZE	7"	SET @	520'	SX. CMT. TOC. Circ
INT.CSG- HOLE SIZE	CSG. SIZE	"	SET @	'	SX. CMT. TOC.
LONG STRING- HOLE SIZE"	CSG. SIZE	4.5"	SET @	3370'	SX. CMT. TOC. 550'
OTHER-					

