

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

MAY 17 2006

2. Name of Operator

Mack Energy Corporation

3. Address and Telephone No.

P.O. Box 960, Artesia, NM 88211-0960

(505)748-1288

4. Location of Well (Footage, Sec., T. R., M. or Survey Description)

660 FSL & 660 FWL, Sec. 25 T16S R31E

5. Lease Designation and Serial No.

NMLC-029492A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Moray Federal #7

9. API Well No.

30-015-04875

10. Field and Pool, or Exploratory Area

Grayburg Jackson SR Q G SA

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work )\*

1. Notify BLM 24 hours prior to starting plugging operations.
2. Set CIBP @ 3566' w/35' cement cap, circ hole with mud. ✓
3. Perf @ 1016' squeeze 100' plug from 1016-916'. WOC and tag. ✓
4. Set 10 sx surface plug. ✓ 0-60'
5. Install dry hole marker.

Note: TOS @ 1015', BOS @ 2015'

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass

Title Production Clerk

Date 5/9/2006

(This space for Federal or State office use)

ORIG. SGD. DAVID R. GLASS

Approved by

Conditions of approval, if any:


Title

**PETROLEUM ENGINEER**

Date

MAY 12 2006

**MACK ENERGY CORPORATION**  
**Moray Federal #7**  
**Sec 25 T16S R31E**



- 1 Notify BLM 24hrs of plugging
- 2 Set CIBP 3566' w/35' cmt cap circ hole w/mud
- 3 Set 100' cmt plug 1016'-916' Perf & squeeze & Tag
- 4 Set 10sk surface plug
- 5 Install dry hole marker

TOS 1015'  
 BOS 2015'  
 QN 3390'