Office	State of New Me	exico	Form C-103			
Office District I	Energy, Minerals and Natu	ural Resources	May 27, 2004			
1625 N. French Dr., Hobbs, NM 88240		Wf	ELL API NO.			
District II	OIL CONSERVATION	IDIVISION	30-005-60143			
1301 W. Grand Ave., Artesia, NM 88210		15	Indicate Type of Lease			
District III	1220 South St. Fra	ncis Dr.	STATE FEE X			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505	State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		OG-1318			
	S AND REPORTS ON WELLS	S 7.	Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PL		AN-EATON LEYENDECKER			
DIFFERENT RESERVOIR. USE "APPLICAT	TION FOR PERMIT" (FORM C-101) F	OR SUCH	Well Number 1			
PROPOSALS.)	7 (1 7 7 2 337 (1		Well Malloci I			
1. Type of Well: Oil Well Gas W		OTHER X	OCDIDAL			
2. Name of Operator	r	15. Visit Visit 9.	OGRID Number			
M.E.W. ENTERPRISE		FEB 2 8 2006 10	D 1 3771			
3. Address of Operator		-   10.	Pool name or Wildcat			
P.O. BOX 39, ROSWELL, NM	88202	JU-AMTERIA				
4. Well Location						
Unit Letter L: 1980 fee	et from the SOUTH line and (	feet from th	e WEST line			
	ownship 6-S Range		County CHAVES			
	1. Elevation (Show whether DR					
The state of the s	4244' GR	i, KKD, KI, OK, cic.)	100000			
Pit or Below-grade Tank Application or C						
		4.6. L4				
Pit type_STEELDepth to Groun		t tresh water well D	stance from nearest surface water			
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Constru	ction Material			
12. Check App	propriate Box to Indicate N	Nature of Notice, Rep	ort or Other Data			
NOTICE OF INTE			QUENT REPORT OF:			
PERFORM REMEDIAL WORK [ F	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐			
TEMPORARILY ABANDON 🔲 (	CHANGE PLANS	COMMENCE DRILLIN	G OPNS.□ P AND A X			
PULL OR ALTER CASING   N	MULTIPLE COMPL	CASING/CEMENT JOI	3 🗆			
OTHER:		OTHER:				
			e pertinent dates, including estimated dat			
	). SEE RULE 1103. For Multip	ole Completions: Attach	wellbore diagram of proposed completion			
or recompletion.						
2-14-06 M.I. R.U.						
	2-15-06 Set C.I.B.P. @4,980 w/35'cmt. on top.					
2-16-06 Spot 25 sx. @4,695'-4,318'. Calc. T.O.C. Cut 4 ½" @3,000'.						
2-17-06 P.O.O.H. w/4 ½".						
2-20-06 Spot 30 sx. @3,050'-2,995'. Measured T.O.C. Plg. Was low. Phil Hawkins o.k. spotting plug @2,854'.						
2-21-06 Tag T.O.C. @2,409'. Witnessed by Russell Whited that covered the 2,570'-2,470'. Plug o.k. by O.C.D.						
			belief. I further certify that any pit or below-			
grade tank has been/will be constructed or clos	sed according to NMOCD guidelines	∐, a general permit ∐ or an	(attached) alternative OCD-approved plan			
SIGNATURE & adaptive	TYTY S	. CDNIT	D. I TO 1.00.00			
SIGNATURE JAMAGELY	TITLE	AGENT	DATE 1-23-06			
Type or print name RANDALI MINI	FAR F-mail address: randall w	inear@hasicenerovservio	ces.com Telephone No. (432) 530-0907			
For State Use Only	L-man addiess, fandall.m					
A State Ost Only		Gerry Guy				
APPROVED BY: / Sluy o	TITLE	Deputy Field Ins				
Conditions of Approval (if any):	THE	District II - Arte	osia DATE			
Constitution of Approval (if any).						
/		*	•			



## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL	RICHARDSON
	Covernor

OR 10 Rolecco 5/26/06 As

Joanna Prukop
Cabinet Secretary
Acting Director
Oil Conservation Division

3 March 2006

M.E.W. Enterprise P. O. Box 39 Roswell, New Mexico 88202

Form C-103 Report of Plugging for your Van-Eaton Leyendecker # 1 L-22-6-27 API 30-005-60143 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been closed as per Rule 50.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name Whitel	MAT I 9 TOO	Van Barton Field Rep II
A service of the serv	OU-ARTES	Markey or Emmandatory Co.  The Broad Society of the Society Organization (Society Organization Company)
Title	a r	The state of the property of the state of th