Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD-HOBBS

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT	5. Lease Serial No. NMNM 35158
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other	8. Well Name and No.
2. Name of Operator CHESAPEAKE OPERATING, INC ATTN: LINDA GOOD	Jill Federal 2 9. API Well No.
3a Address 3b. Phone No. (include area code)	30-005-63182
P.O. BOX 18496, OKLAHOMA CITY, OK 73154-0496 405-767-4275 RECEIVED	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660 FNL 2000 FWL SEC 24 TOS P25F MAY 2, 5 7006	So. Pecos Slope; Abo 11. County or Parish, State
660 FNL 2000 FWL, SEC 24, T9S, R25E	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Acidize	art/Resume) Water Shut-Off Well Integrity Other
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Al ☐ Convert to Injection ☐ Plug Back ☐ Water Disposal	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and the Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Require following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices must be filed only after all requirements, including recland determined that the site is ready for final inspection.) 5/11/2006 MIRU Gray Wire Line Ser. TIH w/4 1/2" CIBP to 4021' & dump 3 sx cmt on plug. To 5/12/2006 MIRU Key Pumping Ser. Circ hole w/64 bbl of salt gel mud. TOOH w/tbg. TIH & p & sqz 40 sx Class "C" neat cmt into perfs & leave 50' plug in csg. Tag plug @ 2443'. Perforate @ cmt in 4 1/2" csg & between 8 5/8' csg to surf. 5/13/2006 RDMO, cut off wellhead, install dry hole marker, cut off guy wire anchors, clean local	red subsequent reports must be filed within 30 days in a new interval, a Form 3160-4 must be filed once nation, have been completed, and the operator has fag plug @ 3990'. Derforate @ 2600' w/4 SPF. TIH w/tbg to 2443' 955' w/4 SPF. Circ 284 sx Class "C" neat
BLM NATIONWIDE BOND #NM2634. (CHK PN 890025) ACCEPTED TO THE CONTROL OF THE CON	ord .
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) LINDA GOOD Title PERMITTING AGE	NT
Signature Linda Gaad Date	05/16/2006
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by CARL SCED DAVID R. GEARS Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	MAY 2 3 2006

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.