



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

Joanna Prukop

Cabinet Secretary

**Lori Wrotenbery**

Director

Oil Conservation Division

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

20-Jun-03

**SHACKELFORD OIL CO**

PO BOX 10665

MIDLAND, TX 79702-0000

## NOTICE OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


### INSPECTION DETAIL SECTION

HADSON FEDERAL 001		O-11-19S-31E		30-015-26524-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/16/2003	MIT Witnessed - Bradenhea	Gerry Guye	Yes	No	7/21/2003	iGEG0308338925
Comments on Inspection:		Violation of Rule 115. Records this office indicate that the 4 1/2 casing was not circulated. A valve must be plumbed to the surface from the 9 5/8 surface to monitor the area behind the production casing. This non-compliance has been active since June 2002.				

HADSON FEDERAL 003		G-11-19S-31E		30-015-26730-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/16/2003	MIT Witnessed - Bradenhea	Gerry Guye	Yes	No	7/21/2003	iGEG0308338920
Comments on Inspection:		Violation of Rule 115. Records this office indicate that the 5 1/2 casing was not circulated. A valve must be plumbed to the surface from the 8 5/8 surface to monitor the area behind the production casing.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.