Form 3160-5 (April 2004)

## UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No. NM-37843

6. If Indian, Allottee or Tribe Name

abandoned w	rell. Use Form 3160 - 3 (A	APD) for such p	proposals.		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name a	and/or No.
1. Type of Well Oil Well 2. Name of Operator Yates Energ 3a Address P. O. Box 2323, Roswell, New 4. Location of Well (Footage, Sec.,	3b. Phone No. (include area code) 432-683-5511  RECEIVED  APR 1 1 2006		8. Well Name and No. Desert Rose Federal No. 1  9. API Well No. 30-015-26167  10. Field and Pool, or Exploratory Area Hess Morrow, East (Gas) Bandana  11. County or Parish, State Eddy, New Mexico		
1740' FSL & 660' FEL of Sec. 27, T23S, R23E					
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NAT	HE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		т	YPE OF ACTION		
✓ Notice of Intent  ☐ Subsequent Report  ☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Constructio Plug and Abandon Plug Back		Well Integrity  ✓ Other Perforate  Abandon	
If the proposal is to deepen din Attach the Bond under which the following completion of the intesting has been completed. Find determined that the site is read.  1.) Pull out of the hole with the site is read.  1.) Pull out of the hole with the site is read.  1.) Pull out of the hole with the site is read.  1.) Pull out of the hole with the site is read.  1.) Run casing inspection.  5.) Repair casing if neede.  6.) Spot 200 gailons acid.  7.) Perforate 4200' to 422.  8.) Go in the hole with co.  9.) Reverse 6 barrels KC.  10.) Displace acid.  11.) Swab/flow test.  12.) Tie into system, run to	ectionally or recomplete horizontally the work will be performed or provisor volved operations. If the operation in all Abandomment Notices shall be to for final inspection.)  th tubing and packer.  72' to 8816' KB.  g and packer plug and abandolog if possible.  d: Run line-up tool, re-cement at 4226' K.B.  6' K.B.  to K.B.  mpletion assembly to approxim L water, space out, set packer a tests as required, put on line.	y, give subsurface loca de the Bond No. on fi results in a multiple co filed only after all requ n perforations 8772 c, drill out or pull ca nately 4100' K.B.	tions and measured and the with BLM/BIA. Requirements, including rectain to 8816' with a CIBI	any proposed work and approximate dura rue vertical depths of all pertinent markers ired subsequent reports shall be filed with in a new interval, a Form 3160-4 shall be mation, have been completed, and the open at 8650' with 35 feet cement on top cement.	s and zones. in 30 days e filed once trator has
14. I hereby certify that the fore Name (Printed/Typed) Sheryl L. Jonas	going is true and correct	Title	Agent for Yates Ene	rgy Corporation	·
Signature All	uld. Jon	Date		04/04/2006	
	THIS SPACE FOR F	EDERAL OR	STATE OFFICE	USE	
Approved by Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant to	l or equitable title to those rights in		Title Office	APPROVED	
Title 18 U.S.C. Section 1001 and Titl States any false, fictitious or fraudul	e 43 U.S.C. Section 1212, make it a lent statements or representations a	crime for any person is to any matter within	knowingly and willfull its jurisdiction.	to make to any department or agency	of the United
(Instructions on page 2)				APR - 6 2006	