

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-05022
5. Indicate Type of Lease STATE ☒ FEE
6. State Oil & Gas Lease No. G-1306
7. Lease Name or Unit Agreement Name Western Development "B" State
8. Well Number 1
9. OGRID Number 013837
10. Pool name or Wildcat Grayburg Jackson SR Q G SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well Other Injection Well ☐	
2. Name of Operator MACK ENERGY CORPORATION	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	
4. Well Location Unit Letter F : 1980 feet from the NORTH line and 1980 feet from the West line Section 36 Township 16S Range 31E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4127' GR	
Pit or Below-grade Tank Application ☒ or Closure ☐	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well 1000' Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material : Above Ground Pit	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5-23-06 Set 5 1/2" CIBP @3,646'. Cap with 35' cement.
5-24-06 Circulate hole with mud. Perf. 4 holes @2,050'. Pressure up to 1500 PSI. Held. Spot 25 sx. cmt. @200'. Tag @184'. Perf. 4 holes @1000'. Set pkr. @631' Squeeze 40 sx. cmt.
5-25-06 Tag plug @874'. Perf. 4 holes @400'. Pump 125 sx. cmt. Down 5 1/2" to surface out of 8 5/8". Leave 5 1/2" full of cement.
5-26-06 Install Dryhole marker.

Approved as to plugging of the well bore. Liability
under bond is retained until surface restoration,
environmental
remediation and final inspection is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed/closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Randall Minear TITLE **P & A SUPERVISOR** DATE: **5-26-06**

Type or print name **RANDALL MINEAR**
For State Use Only

Telephone No. **432-530-0907**

APPROVED BY: _____ TITLE _____ DATE _____
Conditions of Approval (if any): _____