
	DEVON ENERGY	<b>4002</b> /002
Submit 3 Copies To Appropriate District Office	State of New Mexico	2Foffin CTD3
District I Energy	y, Minerals and Natural Resources	May 27, 20040
1625 N. French Dr., Hobbs, NM 88240 Discrict II		WELL API NO. 30-015-21183
1301 W. Grand Ave., Artesia, NM 88210 OIL	CONSERVATION DIVISION	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		5. Indicate Type of Lease AND NED A STATE TEDERAL STATE TEDERAL STATE STATE TO THE STATE OF THE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No. CO - All
1220 S. St. Francis Dr., Santa Fe, NM 87505	· ·	Ca Dos
SUNDRY NOTICES AND R		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL DIFFERENT RESERVOIR. USE "APPLICATION FOR P		Western Reserves Federal 22020
PROPOSALS.)	ERMIT (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well Gas Well	Other	1
2. Name of Operator		9. OGRID Number
Devon Energy Production Company, LP  3. Address of Operator		6137 10. Pool name or Wildcat
20 North Broadway Oklahoma City, Oklahom	a 73102-8260 (405) 552-7802	Avalon (Morrow)
4. Well Location		
	om the North line and 19	80 feet from the west line
Section 4 Township 21S	Range 26E NMPM	County Eddy
	ion (Show whether DR, RKB, RT, GR,	
3208'		
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDk	stance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-G	rade Tank: Volume bbls	Construction Material
12. Check Appropriate	e Box to Indicate Nature of Noti	ce, Report or Other Data
NOTICE OF INTENTION	LTO:	UDGEOUENT BERORT OF
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AN		UBSEQUENT REPORT OF: /ORK
TEMPORARILY ABANDON  CHANGE		DRILLING OPNS. P AND A
		<del></del>
PULL OR ALTER CASING 1 MULTIPLE		
PULL OR ALTER CASING MULTIPLE	CASING/CEI	EN 100B
OTHER: MIT Test & Chart for TA	OTHER:	MIT Test & Chart for TA
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operations.	OTHER:	MIT Test & Chart for TA   , and give pertinent dates, including estimated date
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE R	OTHER:	MIT Test & Chart for TA
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operations.	OTHER:	MIT Test & Chart for TA   , and give pertinent dates, including estimated date
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE R	OTHER:	MIT Test & Chart for TA   , and give pertinent dates, including estimated date
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE Right or recompletion.	OTHER: lions. (Clearly state all pertinent detail: ULE 1103. For Multiple Completions	MIT Test & Chart for TA  s, and give pertinent dates, including estimated date  Attach wellbore diagram of proposed completion
OTHER: MIT Test & Chart for TA  13 Describe proposed or completed operation of starting any proposed work). SEE Right or recompletion.  MIRU pump truck. Bleed air off and tested csg to	OTHER: lions. (Clearly state all pertinent detail: ULE 1103. For Multiple Completions	MIT Test & Chart for TA  s, and give pertinent dates, including estimated date  Attach wellbore diagram of proposed completion
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE Right or recompletion.	OTHER: lions. (Clearly state all pertinent detail: ULE 1103. For Multiple Completions	MIT Test & Chart for TA  s, and give pertinent dates, including estimated date  Attach wellbore diagram of proposed completion
OTHER: MIT Test & Chart for TA  13 Describe proposed or completed operation of starting any proposed work). SEE Right or recompletion.  MIRU pump truck. Bleed air off and tested csg to	OTHER: lions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal	MIT Test & Chart for TA  s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE Rigor recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal	MIT Test & Chart for TA  s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE Rigor recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal	MIT Test & Chart for TA  s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal  for notification. Copy of BLM form t for Mechanical Integrity	Altach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal  for notification. Copy of BLM form t for Mechanical Integrity	Altach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal  for notification. Copy of BLM form t for Mechanical Integrity	Altach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal  1 for notification. Copy of BLM form t for Mechanical Integrity	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.  I hereby certify that the information above is true.	OTHER:  ions. (Clearly state all pertinent detail: ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal for notification. Copy of BLM form t for Mechanical Integrity  ELM CAS WILL e and complete to the best of my know	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.	OTHER:  ions. (Clearly state all pertinent detail: ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal for notification. Copy of BLM form t for Mechanical Integrity  ELM CAS WILL e and complete to the best of my know	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River or recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.  I hereby certify that the information above is true.	OTHER:  ions. (Clearly state all pertinent detail: ULE 1103. For Multiple Completions to 500 psi for 30 min. Lost 20 psi, cal for notification. Copy of BLM form t for Mechanical Integrity  ELM CAS WILL e and complete to the best of my know	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.  Coccepted for record - NMOCD  ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.  I hereby certify that the information above is true grade tank has been/will be constructed or closed according SIGNATURE.	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions  to 500 psi for 30 min. Lost 20 psi, cal  I for notification. Copy of BLM form  t for Mechanical Integrity  As Well  and complete to the best of my knowing to NMOCD guidelines [], a general perm  TITLE Sr. Staff Engineering	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.  Coccepted for record - NMOCD  ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan  Technician DATE 07/31/06
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River and the starting and the st	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions  to 500 psi for 30 min. Lost 20 psi, cal  I for notification. Copy of BLM form  t for Mechanical Integrity  CAS WILL  e and complete to the best of my knowing to NMOCD guidelines [], a general permits	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.  Coccepted for record - NMOCD  ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan  Technician DATE 07/31/06
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.  I hereby certify that the information above is true grade tank has been/will be constructed or closed according SIGNATURE.	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions  to 500 psi for 30 min. Lost 20 psi, cal  I for notification. Copy of BLM form  t for Mechanical Integrity  As Well  and complete to the best of my knowing to NMOCD guidelines [], a general perm  TITLE Sr. Staff Engineering	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.  Coccepted for record - NMOCD  ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan  Technician DATE 07/31/06
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River recompletion.  MIRU pump truck. Bleed air off and tested csg to down, move off.  Copy of OCD form C-103 being sent to the BLM.  Please see attached copy of chart.  I hereby certify that the information above is true grade tank has been/will by constructed or closed according SIGNATURE  Type or print name. Stephanie A. Ysasaga.  For State Use Only.	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions  to 500 psi for 30 min. Lost 20 psi, cal  I for notification. Copy of BLM form  t for Mechanical Integrity  As Well  and complete to the best of my knowing to NMOCD guidelines [], a general perm  TITLE Sr. Staff Engineering	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.  Coccepted for record - NMOCD  ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan  Technician DATE 07/31/06
OTHER: MIT Test & Chart for TA  13. Describe proposed or completed operation of starting any proposed work). SEE River and the starting and	OTHER:  ions. (Clearly state all pertinent details ULE 1103. For Multiple Completions  to 500 psi for 30 min. Lost 20 psi, cal  I for notification. Copy of BLM form  t for Mechanical Integrity  As Well  e and complete to the best of my knowing to NMOCD guidelines [], a general perm  TITLE Sr. Staff Engineerin  E-mail address: Stephanie. Ysasaga@	Attach wellbore diagram of proposed completion  ded Jim Ames w/BLM, will take that for TA. Rig  3160-5 attached.  Test conducted on July 28, 2006.  Coccepted for record - NMOCD  ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan  ing Technician DATE 07/31/06.  dvn.com Telephone No. (405) 552-7802





Form 3160-5 • (August 1999)

its jurisdiction.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APROVED OMB NO. 1004-0135 (PIRES: NOVEMBER 30, 2000

BUREA	U OF LAND MANAGEMENT	_	EXPIRES: NOVEMBER 30, 2000
SUNDRY NOT	ICES AND REPORTS ON WELLS	5. L	ease Senal No.
	m for proposals to drill or to re-enter an e Form 3160-3 (APD) for such proposals	8. m	NM-NN0514348-A Indian, Anottee or Thoe Name
	UBMIT IN TRIPLICATE		
31	COMPLIE THE FORTE	17. U	Init or CA Agreement Name and No.
a. Type of Well Off Well 7 G	ss Well Other		NM 107704
z. Type of theirOn wenG	s wei		ell Name and No.
. Name of Operator			Western Reserves Federal 1
Devon Energy Production (	Co., LP	9. A	PI Well No.
Address and Telephone No.			30-015-21183
20 North Broadway, Ste 15	00, Okiatroma City, OK 73102	<b>405-562-7802</b> 10.	Field and Pool, or Exploratory
	rly and in accordance with Federal requirem		Avaion (Morrow)  County or Parish 13. State
Lot A Sec 28 T-23S-R31E		12.	
660' FNL & 990' FEL			Eddy NM
	APPROPRIATE BOX(s) TO INDIGATE NAT		OTHER DATA
TYPE OS SUBMISSION	<u></u>	TYPE OF ACTION	
Notice of Intent	Acidize Deeper	• • • • • • • • • • • • • • • • • • • •	
_		re Treat Reclamation	☐ Well Integrity ☐ Other ##IT too!
✓ Subsequent Report		ionstruction	The second second
			OBITOM!
sepen directionally or recomplete horizontally, give a se Bond No. on tile with BLM/BIA. Required subsequ travval, a Form 3160-4 shall be filed once testing has	Convert to Injection Plug B	ack Water Disposa: including estimated date of starting any proper of all pertinent markers and zones. Attach the on of the involved operations. If the operation	osed work and approximate duration thereof. If the proposal his Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new
Describe Proposed or Completed Operations ( deepon directionally or recomplete horizontally, give no Bond No. on tile with BLM/BIA. Required subsequenterval, a Form 31604 shall be filed once testing has	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, subsurface location and measured and true vertical depths sent reports shall be filed within 30 days following complete	ack Water Disposa: including estimated date of starting any proper of all pertinent markers and zones. Attach the on of the involved operations. If the operation	osed work and approximate duration thereof. If the proposal his Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new
<ol> <li>Describe Proposed or Completed Operations (seepon directionally or recomplete horizontally, give as the Bond No. on tile with BLM/BIA. Required subsequitorval, a Form 3160-4 shall be filed once testing has elemined that the site is reedy for final inspection).</li> </ol>	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, subsurface location and measured and true vertical depths sent reports shall be filed within 30 days following complete	ack Water Disposa: including estimated date of starting any proper of all pertinent markers and zones. Attach the on of the involved operations. If the operation	osed work and approximate duration thereof. If the proposal his Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new
<ol> <li>Describe Proposed or Completed Operations (ideepen directionally or recomplete horizontally, give a he Bond No. on tile with BLM/BIA. Required subsequiterval, a Form 3160-4 shell be filed once testing has letermined that the site is ready for final inspection).</li> </ol>	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, subsurface location and measured and true vertical depths sent reports shall be filed within 30 days following complete	ack Water Disposa- including estimated date of starting any prop- ic of all perthent markers and zones. Attach it on of the involved operations. If the operation ad only after all requirement, including reclam	osed work and approximate duration thereof. If the proposal he Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new lation, have been completed, and the operator has
13. Describe Proposed or Completed Operations (deepen directionally or recomplete horizontally, give a he Bond No. on file with BLM/BIA. Required subsequiterval, a Form 3160-4 shall be filed once testing has letermined that the site is reedy for final inspection). 07/29/06: MIRU pump truck. Bleed air off and testing the properties of the properties.	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, substrates location and measured and true vertical depths sent reports shall be filed within 30 days following complete been completed. Final Abandonment Notices shall be file	ack Water Disposa- including estimated date of starting any prop- s of all pertinent markers and zones. Attach the on of the involved operations, if the operation and only after all requirement, shoulding reclaim allied Jirm Arnes w/BLM, will take the	osed work and approximate duration thereof. If the proposal he Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new lation, have been completed, and the operator has
IS. Describe Proposed or Completed Operations (deepen directionally or recomplete horizontally, give a the Bond No. on tile with BLM/BIA. Required subsequiterval, a Form 3160-4 shell be filed once teeting has between inetermined that the site is ready for final inspection).  107/29/06:  MIRU pump truck. Bleed air off and test Copy of BLM form 3160-5 being sent to the site is sent to	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, substrates location and measured and true vertical depths sent reports shall be filed within 30 days following complete a been completed. Final Abandonment Notices shall be file and the complete of the file of the complete of the file of the complete of the file	ack Water Disposa- including estimated date of starting any propi of all pertinent markers and zones. Attach it ion of the involved operations. If the operation ad only after all requirement, including reclam allied Jim Ames w/BLM, will take the	osed work and approximate duration thereof. If the proposal his Bond under which the work will be performed or provide in results in a multiple completion or recomplistion in a new lation, have been completed, and the operator has not for TA. Rig down, move off.
13. Describe Proposed or Completed Operations (deepen directionally or recomplete horizontally, give a the Bond No. on the with BLM/BIA. Required subsequiterval, a Form 3160-4 shall be filed once teeting has determined that the site is reedy for final inspection).  107/29/06:  MIRU pump truck. Bleed air off and test Copy of BLM form 3160-5 being sent to the site is reedy for final inspection.	Convert to Injection Plug B. Clearly state all perthent details, and give pertinent dates, substrates location and measured and true vertical depths shall be filed within 30 days tollowing complete been completed. Final Abandonment Notices shall be file details be filed to be filed within 30 min. Lost 20 psi, call the NMOCD. Copy of NMOCD form attaches that for Mechanical Integration of the filed within and corract.  Name St.	ack Water Disposa. Including estimated date of starting any proper of all perthent markers and zones. Attacht it on of the involved operations. If the operationed only after all requirement, including reclaim allied Jim Ames w/BLM, will take the od.  Trity Test conducted apphanic A. Yeasaga	osed work and approximate duration thereof. If the proposal he Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new lation, have been completed, and the operator has not for TA. Rig down, move off.  on July 28, 2006.
3. Describe Proposed or Completed Operations ( Jespan directionally or recomplete horizontally, give a he Bond No. on tile with BLMBIA. Required subsequenterval, a Form 3180-4 shall be filed once testing has letermined that the site is ready for final inspection)  0.7/29/06:  MIRU pump truck. Bleed air off and test  Copy of BLM form 3180-5 being sent to  Please see attached cl  14. Thereby certain that the topegoing is  Signed	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, substrates location and measured and true vertical depits about reports shall be filed within 30 days following complete been completed. Final Abandonment Notices shall be filed csg to 500 pai for 30 min. Lost 20 psi, can the NMOCD. Copy of NMOCD form attached than the for Mechanical Integration of the complete shall be filed to the NMOCD.  True and correct  Name Static Sr. Static controls of the co	ack Water Disposa. Including estimated date of starting any proper of all perthent markers and zones. Attacht it on of the involved operations. If the operation of only after all requirement, including reclamation of the properties of only after all requirement, including reclamation of the properties of only after all requirement, including reclamation of the properties of the propertie	osed work and approximate duration thereof. If the proposal his Bond under which the work will be performed or provide in results in a multiple completion or recompletion in a new lation, have been completed, and the operator has not for TA. Rig down, move off.
is. Describe Proposed or Completed Operations ( deepen directionally or recomplete horizontally, give a he Bond No. on the with BLM/BLA. Required subsequenterval, a Form 3160-4 shall be find once testing has determined that the site is ready for final inspection)  07/29/06:  MIRU pump truck. Bleed air off and test  Copy of BLM form 3160-5 being sent to the site is seen attached city.  Please see attached city.  14. Thereby certury that the topegoing is	Convert to Injection Plug B. Clearly state all pertinent details, and give pertinent dates, substrates location and measured and true vertical depits about reports shall be filed within 30 days following complete been completed. Final Abandonment Notices shall be filed csg to 500 pai for 30 min. Lost 20 psi, can the NMOCD. Copy of NMOCD form attached than the for Mechanical Integration of the complete shall be filed to the NMOCD.  True and correct  Name Static Sr. Static controls of the co	ack Water Disposa. Including estimated date of starting any proper of all perthent markers and zones. Attacht it on of the involved operations. If the operationed only after all requirement, including reclaim allied Jim Ames w/BLM, will take the od.  Trity Test conducted apphanic A. Yeasaga	osed work and approximate duration thereof. If the proposal he Bond under which the work will be performed or provide in results in a multiple complistion or recomplistion in a new lation, have been complisted, and the operator has not for TA. Rig down, move off.  on July 28, 2006.

\*See Instruction on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willufly to make any department or agency of the United States any false, ficilitious or fraudulent statements or representations to any matter within

