

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87401

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30.015.00716

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Empire Abo Unit "K"

8. Well Number

15

9. OGRID Number

000778

10. Pool name or Wildcat

Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

BP America Production Company

3. Address of Operator

P.O. Box 1089, Eunice, NM 88231

4. Well Location

Unit Letter J : 1980 feet from the S line and 1980 feet from the E line

Section 2 Township 18S Range 27E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6100' PBD: 6020' (CIBP) PERFS: 5348-6000'

07.22.03: MIRUPU. NDWH. NUBOP. Hot oil tbg & POH.

07.23.03: RIH w/bit & scraper testing tbg in hole. Tag @ 6007'. POH. RIH w/CIBP @ 6020'. RU pmp truck & pmp 15 bbls on csg to top of plug. RIH w/logging tools, log well, & POH.

07.24.03: RU & perf 5348-6000'.

07.25.03: RIH w/pkr, SN, & tbg to 5154'. SIFW

07.28.03: RIH to 6007'. RU acid trucks. Spot 15% HCL NEFE. PUH 13 jts & set pkr @ 5615'. Pmp 1st stage 15% HCL NEFE acid job. Unset pkr. POH w/tbg & pkr. PU plug & RIH w/ plug, pkr, SN & tbg. Set plug @ 5615'. Spot acid. PUH 4 jts. Set pkr @ 5497'. Pmp 2nd stage 15% HCL NEFE acid job. Unset pkr. RIH w/4 jts & unset plug. PUH 4 jts & set plug @ 5497'. Spot acid. PUH 8 jts & set pkr @ 5253'. Pmp 3rd stage 15% HCL NEFE acid job. Unset pkr. RIH 8 jts & unset BP. POH.

07.29.03: RIH to 6028' & clean out frac balls. POH. RIH w/production assy. NDBOP. NUWH. RTP. In 24 hrs pmp 234 MCF, 1 BO, 35 BW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Admin. Asst. DATE 08.13.03

Type or print name Kellie D. Murrish E-mail address: murrikd@bp.com Telephone No. 505.394.1649

(This space for State use)

FOR RECORDS ONLY

AUG 18 2003

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any: