Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103 Revised March 25, 1999			
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WEL	WELL API NO.			
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION				5-60648			
District III	1220 South St. Francis Dr.			5. Inc	licate Type o		·•	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505				STATE L	J FEE X		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM		5 , 1 (2)1		6. S	tate Oil & G	as Lease No.	***************************************	
	CES AND REPORTS OF			7. Le	ase Name or	Unit Agreement N	ame:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Twin	Twin Lakes San Andres Unit			
1. Type of Well: Oil Well Gas Well	Other INJECTI	ION /						
2. Name of Operator			2001 HA	\ \ \ 8. W	ell No.			
Tipton Oil & Gas Acquisitions, Inc.		N	Court 3 Silly MA	2			***************************************	
3. Address of Operator	ions, Inc. NM 88260				9. Pool name or Wildcat			
P.O. Box 1234, Lovington, NM 88260				Twin	Twin Lake, San Andres (Assoc)			
4. Well Location								
Unit Letter K 1650	feet from the _SOU	тн	line and _	2310	feet from	the WEST	_line	
Section 25	Township 8S	Range	28E	NMPI	M Chaves,	, County		
	10. Elevation (Show v	whether D	R, RKB, RT, G	R, etc.)			e Security	
11 Cl1- A		1: NT	-4 CNT-4	·	041	Data		
	opropriate Box to In	dicate N						
NOTICE OF INT PERFORM REMEDIAL WORK ☐			REMEDIAL			PORT OF: ALTERING CASI	ис ГП	
FERI ORWINEWIEDIAE WORK	PLOUPAIND ABAINDON	• 📖	REWEDIAL	WORK		ALTERING CASI	1 G 🗀	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE	E DRILLING	OPNS. 🗌	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB					
	COM LETICIT						1	
OTHER:		<u> </u>	OTHER: R					
12. Describe proposed or complete of starting any proposed work).								
or recompilation.	SEE RULE 1103. FOI	Multiple	completions: 7	Attach wend	ore diagram	or proposed compre	HOII	
0x 1000214 11011011								
2 (2 (2 =								
2/8/07 POOH w/tbg. & pkr. Run new tbg	and pler							
Pressure test to 500# psi, okay. Ch	-							
Returned to injection – 28 BWPD								
I hereby certify that the information	above is true and compl	lete to the	best of my kno	wledge and	belief.			
// -	7		•	J				
SIGNATURE CL	TITLE	Clay Tip	ton (Sec-Treas	.) DATE	2/8/07			
Type or print name Clay Tip	ton Telephone	No. 505-	631-4121					
(This space for State use)		_	ccepted to	r record				
APPPROVED BY		TITLE	YMMA	(A)		DATE		
Conditions of approval, if any:		_********		1				

