Form 3160-5 (February 2005) N.M. Oil Cons. Day

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MARSHER VI

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

LC069 280-A

6. If Indian, Allottee or Tribe Name

Month - Year MAR 2 3 2007 OCD - ARTESIA, NM SUNDRY NOTICES AND REPORTS ON WELLS

Change Plans

Convert to Injection

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

IA, NM	en. Use Porm 3160-3 (APD) for such pro	posais.			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. SULIMAR QUEEN UNIT 8. Well Name and No.	
1. Type of Well Gas Well Other						
2. Name of Operator NEW MEXICO INSTITUTE OF MINING & TECHNONOGY					SULIMAR QUEEN UNIT TR 1 & 2 9. API Well No.	
3a Address		3b. Phone No. (include area code)		30-005-60068		
D.Cox, SNL MS 0778, Box 5800, Albuquerque, NM 87185-0778 505-284-3871				10. Field and Pool, or Exploratory Area SULIMAR QUEEN		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						
1980' FNL 1980' FWL U/L F SEC24# T15S R29E				11. County or Parish, State		
				CHAVES	COUNTY, NEW MEXICO	
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RI	EPORT, OR C	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	Deepen	Production (Sta	rt/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Ĺ	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

SEE ATTACHMENT

Temporarily Abandon

Water Disposal

NMOCD .

APPROVED AS TO PLUGGING OF THIS
WELL BORE. LIABILITY UNDER BOND
IS RETAINED UNTIL SURFACE RESTORATION
IS COMPLETED

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)							
Jack B. TILLman		SNL Field Re	presentative				
	Title						
Signature Joseph of Sellman	Date	03/16/07					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
I III O I AGET ON EDEIGNE ON OTATE OF THE GOL							
Approved by /S/ DAVID R. GLASS	#	ETROLEUM ENGINEER	Date MAR 2 0 2007				
Conditions of approval, if any, are attached. Approval of this notice does not warrantee	ent or						
certify that the applicant holds legal or equitable title to those rights in the subject le	1						
which would entitle the applicant to conduct operations thereon.		Office					
Tid 19 HCC Carta 1001 at Tid 42 HCC Carta 1212 advita air Carra la include de la inferiore de							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.

Final Abandonment Notice

MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

NEW MEXICO INSTITUTE OF MINING & TECHNOLOGY

Lease: SULIMAR QUEEN UNIT TR 1 # 2

Project: P & A – CEMENTING REPORT API # 30-005-60068

03-23-06 - SPOT 25 SXS @ 1950'-1950' TAGGED

03-24-06 – SPOT 25 SXS @ 1950'-1874' TAGGED

03-24-06 - LOCATE HOLES @ 1874'-1764'

03-24-06 - SPOT 25 SXS @ 1874'-1798' - TEST CASING TO 500#

03-27-06 - PERFORATE @ 1270' - SQUEEZE 80 SXS @ 1270'-972' - TAGGED

03-27-06 - PULL 467' OF 5 1/2" CASING

03-27-06 - SPOT 60 SXS @ 512'-332' & TAG

03-28-06 - PERFORATE @ 258' - SPOT 35 SXS @ 315'-211' & TAG

03-28-06 - SPOT 60 SXS @ 189'-22' & TAG

03-28-06 - SPOT 10 SXS @ 22' TO SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10# MUD