Form 3160-5

OCD-ART **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

A	FORM APPROVED
	OMB No. 1004-0137
	Expires: March 31, 2007
	5. Lease Serial No.

OCD.

onth - Year \		NM-0/4	333			
SUNDRY N Do not use this f ARTESIA, Nultyandoned well.	IOTICES AND REPORT form for proposals to d Use Form 3160-3 (APD	6. If Indian, A	llottee or Tribe Name			
SUBMIT IN TRIPLICATE – Other Instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas Well Other Water Injection			8. Well Name LOCO H	8. Well Name and No. LOCO Hills A Federal 5		
2. Name of Operator CBS Operating Corp.				9. API Well No. 30-015-20610		
3a. Address P O Box 2236 3b. Phone No. (include			(e) 10. Field and I	Pool or Exploratory Area		
Midland TX 797	32/685-0878	Graybur	Grayburg Jackson SR QN G SA			
4. Location of Well (Footage, Sec., T.) 1980' FSL & 660' FWL	S R30E		11. Country or Parish, State Eddy NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Red	Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	Other		
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporarily Abando Water Disposal	n	 	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 1. MI&RU pluggers. Rig up steel pit. 2. RIH and set 5-1/2" CIBP @ 2560'. 3. RIH with work string to 2560' and circulate drilling mud. Spot 25 sacks cement @ 2560', tag. 4. Cut and pull casing as determined on location. 5. Spot 100' cement plug 50' in and 50' out of casing cut off. Tag. This plug should cover base of salt @ 1100'+ TAG. 6. Spot 100' cement plug across top of salt 50' inside surface shoe 50' outside. Top of salt @ 530'+, surface casing shoe @ 510'. TAG. 7. Pull up to 60' circulate, 15 sacks cement to surface. 8. Cut off wellhead, install dry hole marker. Cut off anchors, clean location, remove any caliche, cut, level and reseed pad.						
			;	APPROVED		
14. I hereby certify that the foregoing is to Name (Printed/Typed) M. A. Sirgp, III	rue and correct.	Title Engi	neer	APR 1 8 2007		
Signature L	Suga #	_{Date} Apri	1 10, 2007	LES BABYAK PETROLEUM ENGINEER	3	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						

Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. SEE ATTACHED FOR CONDITIONS OF APPROVAL

Title Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements Or representations as to any matter within its jurisdiction.

,	K.B.ELEV.: K.B.CORRECTION:
HOLE SIZE: /2'14"	G.L.ELEV.: 3697 85/8" 24 # GRADE SET AT 5/0 CEMENT WITH 150 SX
HOLE SIZE: 77/8 "	PERFS: 2656-59' 2668-71' PERFS: 2678-82' 2724-28' PERFS: 2764-68' 2780-84' PERFS: 2795-98' 2820-24' PERFS: 2863-68'
HOLE SIZE: "	5
FIELD: FORMATION:	GERMI WITH 430 OK STOS
PBTD <u>2890'</u> TOTAL DEPTH: <u>2893'</u>	Accepted for record NMOCD
API NO. 30-015-20610	
LEASE NAME: LOCO HILLS A FEDERAL	WELL NO.:
WELLBORE DIAGRAM AS OF DATE: MAY 16, 200	5
STATE: NEW MEXICO COUNTY: EDDY	BLOCK: UL L SECTION: 10
TOWNSHIP: 17S RANGE: 30E	
OPERATOR: CBS OPER CORP WORKING INTEREST:	
COMPLETION DATE: 5-11-72 CURRENT STATUS: (P	·
REMARKS: 6-19-75 Convert to water inject	