## District I

PO Box 1980, Hobbs, NM 88241-1980

District II

PO Drawer DD, Artesia, NM 88211-0719

Previous Operator Signature

**State of New Mexico** 

Energy, Minerals & Natural Resources Department Month - Year OIL CONSERVATION DIVIS ON ARTESIA, NM

Form C-104 Revised October 18, 1994 Instructions on back Appropriate District Office

District III 2040 South								1	N. Carlotte				5 Copies
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe				e, NM	87505		1		/_				
District IV									_			AME	NDED REPORT
2040 South Pa				OWAD.	Y PE A NITS A	TITLL	10 T/7 A 1	TIA	יי איי איי	ו א כווים	MODON	· OF	
I.	REQ			***	LE AND A	MIHO	KIZA	ПО	NIUI				
	Deve	1	tor Name and . Production		ı, I D		<sup>2</sup> OGRID Number <b>6137</b>						
			y, Suite 150		, 1.1		Reason for Filing Code						
			, OK 7310				NW						
	Number					Pool Name							
<del></del>	-015-34					Praw; Mo					<u>, ,,</u>	30	
Prope	erty Code				Property Na	perty Name o <b>6 State</b>					Well Nu		
II. <sup>10</sup> Sur	oface I	Location			Otor	IIIO O SIA	te						<u> </u>
UI or lot no.	Section	Township	Range	Lot.Idn	Feet from the	North/So	oth I ine	Treet	from the	Fast/V	West Line	<del></del>	County
H	6	23S	26E	Lot.iun	1330		RTH	Feet	690		EAST		EDDY
		Tole Loca			1				<u> </u>	4			
		Township	Range	Lot.Idn	Feet from the	North/So	uth Line	Feet	from the	East/V	West Line	T	County
								<u> </u>		<u> </u>		<u> </u>	
12 Lse Code	13 Produ	cing Method (	Code	le 14 Gas Connection Date 1		<sup>15</sup> C-129 Pe	C-129 Permit Numbe		per <sup>16</sup> C-129 Effecti		ve Date 17 C-129 Expiration Date		Expiration Date
S	L	<u> </u>		3/7/	/2007								
		as Trans	porters	10			20		1 21	<del></del>	22		
" Trans	sporter			Transporte and Add			<sup>20</sup> POD <sup>21</sup> O/G		<sup>21</sup> O/G		POD ULSTR Location and Description		
	51618		Enterp		Services LL	$\overline{\mathbf{c}}$			G	and Description			IOII
			Pos	st Office l	Box 4324	Ì			1	1			
			Hous	ton, TX	77210-4324								
										1			
						L							
										1			
										Í			
										1			
										4			
IV. Prod	duced	Water								4			* 11.5925
17. 110.	POD	Water_	<del></del>			24 POD UL	STR Loca	tion ar	nd Descripti	ion			
	102					102 0_	J111 2002	HUII u	W 12020-1-	011			
V. Well	Comp	letion D	ata										
25 Spud Date		26 Ready					<sup>26</sup> PBTD <sup>29</sup> Perforat		itions	$\neg I$	30 DHC,	, DC, MC	
12/24/2	ባባΚ	3/7	//2007	007 11,715'		116	11,670' 11,262' -		11,262' -1	1 2751			
	Hole Siz			32 Casing & Tubing Size				33 Dep		1,2/3	34	Sacks C	ement
	17 1/2			13 3/8"			714'						C, 141 to pit
	12 1/4			9 5/8"			1629'						C, 167 to pit
	8 3/4"			5 1/2"			11715'				3020	0 sx Cl I	H/C 53 to pit
377 33761	· Track	D-4-											
	l Test New Oil		as Delivery Da		37 Test Date	_	38 Test Let	- cth	1 3	9 Than 1	Pressure		<sup>40</sup> Csg. Pressure
3/7/2007		•	3/7/2007 4/9/2007			24		I vg. a	,		Csg. Ficssure		
		<sup>42</sup> Oil				44 Gas		45	<sup>45</sup> AOF <sup>46</sup> Test Method		46 Test Method		
	/64"		0		99		485						Flowing
	•				have been comp								
with and that the information given above is true and complete to the best of my					у	O	IL C	CONSER	VAT	ION DI	VISIO	N	
knowledge and belief.				1.	BRYAN G. ARRANT								
Signature: Printed Name: Stephanie A. Ksakaga						Approved by: DISTRICT II GEOLOGIST							
Title: St. Staff Engineering Technician					_	Title: Approval Date:							
Date: 4/10/2007 Phone: 405-552-7802					гругот	MAY 0 8 2007							
If this is a change of operator fill in the OGRID number and name of the previous						evious oper	etor				<u></u>	₩ 8	2007
11 0113 13 14	change of	operator iii i	# ale odkab	number and	a name of the pro	evious open	ator						

Printed Name

Title

Office	State of New Mexic	U	Form C-103
District I	Energy, Minerals and Natural	Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL A	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DI	VISION.	30-015-34941
District III	1220 South St. Francis	5. Indica	e Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8750:		ATE FEE
District IV	Santa re, Nivi 6/30.	6. State C	Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		D = ARTESIA, NM	
	CES AND REPORTS ON WELLS	7. Lease	Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS.	ALS TO DRILL OR TO DEEPEN OR PLUG B	ACK TO A / Ocotillo 6	
	ATION FOR PERMIT" (FORM C-101) FOR SU	8. Well N	Jumber
PROPOSALS.)  1. Type of Well: Oil Well	Gas Wall M Other	1	
2. Name of Operator	Jas Well 🔼 Other		O Number
Devon Energy Production Company	I D	6137	J Number
3. Address of Operator	, 11		name or Wildcat
20 North Broadway Oklahoma City	v Oklahoma 73102-8260 (405) 5		aw; Morrow
	,, GRIANOMA 75102 0200 (105) 5	Short Birds	,
4. Well Location			
	feet from theNorth line and		
Section 6 Townshi	<u> </u>		unty, NM
	11. Elevation (Show whether DR, RK	B, RT, GR, etc.)	
	3396'		
Pit or Below-grade Tank Application or	Closure   _		
Pit typeDepth to Groundwar	terDistance from nearest fresh water	well Distance from ne	arest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction M	aterial
12 Charle A	ppropriate Box to Indicate Natu	ra of Nation Donart or	Other Date
12. CHECK A	ppropriate box to findicate Natu	ie of Notice, Report of	Other Data
NOTICE OF IN	TENTION TO:	SUBSEQUE	IT REPORT OF:
PERFORM REMEDIAL WORK		EMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	<del></del>	DMMENCE DRILLING OPN	
PULL OR ALTER CASING		ASING/CEMENT JOB	
TOLE STORETER OF SING		IOITO/OLINEITI OOD	
OTHER:	□   o-	THER: COMPLETION R	EPORT 🛛
	eted operations. (Clearly state all perti	nent details, and give perti	nent dates, including estimated date
	LA OPERATERIAN PARAMETA O	ompletions: Attach wellbo	re diagram of proposed completion
	K). SEE KULE 1103. For Multiple C		
	k). SEE RULE 1103. For Multiple C		
of starting any proposed wor	k). SEE RULE 1103. For Multiple C		
of starting any proposed wor	k). SEE RULE 1103. For Multiple C		
of starting any proposed wor or recompletion.	k). SEE ROLE 1103. For Multiple C		
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:	st csg to 1500# - ok. RU swivel, drl	out dv tl @ 4495', RD sw	ivel. PBTD @ 11,670'. RU swivel,
of starting any proposed wor or recompletion. 02/14/07 – 0307/07: MIRU. NU BOP, PU bit & tbg. Te			
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11,	275'; (4SPF) 52 holes. Se	t pkr w/2.31 F nipple & tbg disk on
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl	st csg to 1500# - ok. RU swivel, drl	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab.
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 600# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn
of starting any proposed wor or recompletion.  02/14/07 – 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl w/29,000# gals Soectra-Star 3000. R	st csg to 1500# - ok. RU swivel, drl 600# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m /D tree saver, open well, flw bck. Swa	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' d b. Put well onto production	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl w/29,000# gals Soectra-Star 3000. R	st csg to 1500# - ok. RU swivel, drl 00# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Tedrill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl w/29,000# gals Soectra-Star 3000. R	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swab	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Te drill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl w/29,000# gals Soectra-Star 3000. R	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swabove is true and complete to the best of lessed according to NMOCD guidelines  a  a	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.  I further certify that any pit or belowed) alternative OCD-approved plan .
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Tedrill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 blw/29,000# gals Soectra-Star 3000. R	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swabove is true and complete to the best of lesed according to NMOCD guidelines, a	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production of my knowledge and belief general permit  or an (attach taff Engineering Technicia	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.  I further certify that any pit or belowed) alternative OCD-approved plan  DATE05/02/07
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Tedrill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 blw/29,000# gals Soectra-Star 3000. R  I hereby certify that the information a grade tank has been/will be constructed of c SIGNATURE  Type or print name Stephanie A. Y	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swabove is true and complete to the best of lesed according to NMOCD guidelines, a	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production of my knowledge and belief general permit  or an (attach taff Engineering Technicia	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.  I further certify that any pit or belowed) alternative OCD-approved plan .  DATE05/02/07  Telephone No. (405) 552-7802
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Tedrill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 blw/29,000# gals Soectra-Star 3000. R  I hereby certify that the information a grade tank has been/will be constructed of c SIGNATURE  Type or print name Stephanie A. Y For State Use Only	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swab bove is true and complete to the best of lesed according to NMOCD guidelines \( \Bar{\text{l}} \), a sasaga  E-mail address: Stephan	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production of my knowledge and belief general permit  or an (attach taff Engineering Technicia	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.  I further certify that any pit or belowed) alternative OCD-approved plan .  DATE05/02/07  Telephone No. (405) 552-7802
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Tedrill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 bl w/29,000# gals Soectra-Star 3000. R  I hereby certify that the information a grade tank has been/will be constructed of c SIGNATURE  Type or print name Stephanie A. Y For State Use Only	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swab bove is true and complete to the best of lesed according to NMOCD guidelines \( \Bar{\text{L}}, a \) and \( \Title{\text{TITLE}} \) Sr. S sasaga \( \text{E-mail address: Stephane Seconds on LY} \)	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production of my knowledge and belief general permit  or an (attach taff Engineering Technicia	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.  I further certify that any pit or belowed) alternative OCD-approved plan .  DATE05/02/07  Telephone No. (405) 552-7802  MAY 0 3 2007
of starting any proposed wor or recompletion.  02/14/07 - 0307/07:  MIRU. NU BOP, PU bit & tbg. Tedrill out dv tl @ 7972'. Tst csg to 15 bttm of pkr @ 11,200'. Bled dwn, fl Acidize w/1000 gals isosol + 100 blw/29,000# gals Soectra-Star 3000. R  I hereby certify that the information a grade tank has been/will be constructed of c SIGNATURE  Type or print name Stephanie A. Y For State Use Only	st csg to 1500# - ok. RU swivel, drl 100# - ok. Swab. Perf @ 11,263'- 11, w bck. TIH w/on/off tl & tbg. NU/D l slrs. Swab. RU tree saver, frac m/D tree saver, open well, flw bck. Swab bove is true and complete to the best of lesed according to NMOCD guidelines \( \Bar{\text{l}} \), a sasaga  E-mail address: Stephan	275'; (4SPF) 52 holes. Se N/BOP; NU tree. RU kil rrw @ 11,262'- 11,275' dib. Put well onto production of my knowledge and belief general permit  or an (attach taff Engineering Technicia	t pkr w/2.31 F nipple & tbg disk on trk, pmp 56 bbls 2% KCL. Swab. wn 2 7/8" tbg w/54,000# 18/40 sn n.  I further certify that any pit or belowed) alternative OCD-approved plan .  DATE05/02/07  Telephone No. (405) 552-7802

## McVAY DRILLING COMPANY

P.O. Box 2450 Hobbs, New Mexico 88241 (505) 397-3311

FAX: 39-DRILL

Well Name and Number: Ocotillo 6 St # 1

Location: Sec 6, T23S, R26E, Eddy County, NM

Operator: Devon

**Drilling Contractor: McVay Drilling Company** 

The undersigned certifies that he is an authorized representative of the drilling contractor who drilled the above described well and that he has conducted deviation tests and obtained the following results:

Degrees @	Depth	Degrees @ Depth			
1 1/4	250	1	7149		
2	475	1 3/4	7647		
2 1/2	714	1 1/2	8115		
2	847	1	8585		
1 1/4	1061	1	9084		
1	1310	1 1/4	9557		
1 1/4	1629	3/4	10050		
1/2	2121	1	10542		
3/4	2620	1	11021		
1	3105	1/2	11690		
1	3583				
1	4057				
3/4	4535				
3/4	5005				
1/2	5504				
3/4	6002				
1 1/4	6499				
1	6683				

Drilling Contractor: McVay Drilling Company

Subscribed and sworn to before me this Haday of

, 2007

My Commission Expires: B-1609

**Notary Public** 

Lea County, New Mexico

