Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
Pistrict I	Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	AL CONGRESS AND DIVISION	30-005-62554
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE S FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	MM	2 2007
	TICES AND REPORTS ON WELLS	7 7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPL	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	East Wind AME State Com
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well Other P&A	8. Well Number
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporat	ion	025575
3. Address of Operator		10. Pool name or Wildcat
105 S. 4 <sup>th</sup> Street, Artesia,	NM 88210	Foor Ranch; Pre-Permian
4. Well Location Unit Letter G:	1980 feet from the North line and	1980 feet from the East line
Section 17	Township 9S Range 27E	NMPM Chaves County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3829'GR		
Pit or Below-grade Tank Application		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mi		Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data		
NOTICE OF I	NTENTION TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING		
TEMPORARILY ABANDON		RILLING OPNS. PLUG AND ABANDON
PULL OR ALTER CASING	MULTIPLE COMPL   CASING/CEMEN	NT JOB
OTHER: OTHER:		
	pleted operations. (Clearly state all pertinent details, a	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
5/16/07 – Set a 5-1/2" CIBP at 6130' with 35' cement on top.		
5/17/07 – Spotted 35 sx cement at 6100' and WOC. Tagged at 5828'. Spotted 25 sx cement at 5400'.		
5/18/07 – Tagged at 5093'. Perforated at 4723'. Spotted 40 sx cement.		
5/21/07 – Tagged at 4085'. Perforated at 2502'. Spotted 25 sx cement at 2250'.		
5/22/07 - Perforated at 1002'. Pumped 40 sx cement and WOC. Tagged at 835'. Perforated at 60' and circulated 15 sx cement to		
surface.		
5/23/07 – Cut off wellhead and installed dry hole marker. <u>WELL IS PLUGGED AND ABANDONED</u> . <u>FINAL REPORT</u> .		
Plugging of the well bore.		
	ler bond is retained	
until surface restoration,		
_	tal remediation and	
final inspect	tion is completed.	
	<b>\</b>	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.		
SIGNATURE (	TITLE Regulatory Compliance	Supervisor DATE May 24, 2007
Type or print nameTina Hud	E-mail address:tinah@ypcnm.	<u>com</u> Telephone No. <u>505-748-1471</u>
For State Use Only	es Juny Gony	<b>'Guye</b> 4 200
APPROVED BY:	TITLE Deputy Field	d Inspector DATE JUN 4 ZUU
Conditions of Approval (if any):	District II	- Artesia