Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103		
Office <u>District I</u>	Energy, Minerals and Natural Resources			Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-10154 5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE [FEE	
District IV	Santa Fe, NM 87505			6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505					E-9262	
SUNDRY NOTI	CES AND REPORTS ON	WELLS		7. Lease Name of	or Unit Agreement Name	,
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK-TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 11/2/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3				North B	enson Queen Unit	
PROPOSALS.)	SATION FOR EDMIT (FORM	(C-101)1.0	Agoen 12/3/2	8. Well Number		
1. Type of Well:		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	☆ ଏ	. Well Number	27	
	Other Injection Wel	11 \(\ldots\)	SEP 2003			
2. Name of Operator	NATA AND THE SECOND TO A SECOND		RECEIVED	95 OGRID Numi		
3. Address of Operator	Minerals Limited Partne	ersnip	OCD - ARTESIA	APO. Pool name o	5300 r Wildcat	
-	bank Dr., Austin, TX 787	10		()	en - Grayburg	
4. Well Location		7.5.5	> 10			
			\$3292 77 CO			
Unit Letter P	: <u>660</u> feet from the _	South	line and6	feet from t	the <u>East</u> line	
Section 29	Township 18	S Ra	nge <u>30E</u>	NMPM <u>Eddy</u>	County	
	11. Elevation (Show whe					
STRUMENTS ASSESSMENT		3414'				
	Appropriate Box to Ind	licate N				
NOTICE OF IN			'	SEQUENT RE		~
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	< Ц	ALTERING CASING [لـ
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRII	LLING OPNS.	PLUG AND	ב
			•	_	ABANDONMENT	_
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	1D 🗀		
	00Mi E2110M				_	
OTHER:	·		OTHER:			
 Describe proposed or comp of starting any proposed we or recompletion. 						
Run Mechanical Integrity test –	test at min 500 nei nressu	re for 30	minutes: record with	h a chart and give	notice to OCD for witne	ee.
Run Weenamear miegrity test –	test at film. 500 psi pressu	10 101 30	minutes, record with	ii a cliait and give	notice to OCD for writing	33.
Operator will use current pack						
isolate perfs. as per Ms. Patton	on 9-					
15-03 via phone call. Notify OC prior to te				D <u>24 how</u>	<u>'S</u>	
			amiam to tes	of 748-128	13	
			Mor to me	yt. / 10 1220		
I hereby certify that the information	above is true and complete	to the be	est of my knowledge	e and belief.		
CHONGE MAG	0. D				D 4 FFF 0 14 0 18 0 0	
SIGNATURE May Cun	less allon	TILE_R	egulatory Coordin:	ator	DATE <u>9/10/2003</u>	_
Type or print name Mary Curl	liss Patton E-n	nail addre	ess: mpatton@uo	minc.com Tele	phone No. (512) 328-81	184
(This space for State use)	700		1 -11	//	3.5 %	
			July 8	SO EN	PROVED SEP 1	6 280
APPPROVED BY Conditions of approval, if any:	TO \	ITLE		-	DATE	
Conditions of approval, it ally.				•		