Form-0160-5 (August 1999)

(This space for Federal or State Office use)

Conditions of approval, if any

Approved by

its jurisdiction

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED
OMB NO. 1004-0135
PIRES NOVEMBER 30, 2000

(REAU OF LAND MANAGEMENT		EXPIRES. NO	OVEMBER 30, 2000
SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals			NM-025604 6. If Indian, Allottee or Tribe Name	
abandoried well		ni proposais	e. If Indian, Allottee of	The Name
	SUBMIT IN TRIPLICATE		7. Unit or CA Agreeme	ent Name and No
1a. Type of Well	A Gas Well Other	JUN 25 2007	7. Chile of C/(/\green\)	she riamo ana rio.
	Gas Weii Guilei		8 Well Name and No	
2. Name of Operator		OCD-ARTESIA	Hawk 9 G Federal 9	
DEVON ENERGY PRO	DUCTION COMPANY, LP		9 API Well No	
3. Address and Telephone No.			30-0)15-29155
20 North Broadway, Oklahoma City, OK 73102 405-552-8198			10 Field and Pool, or Exploratory	
4 Location of Well (Report location clearly and in accordance with Federal requirements)*			Red Lake; Queen Grayburg San Andres	
1650' FNL & 2310' FEL, Sec. 9-T18S-R27E, Unit "G"			12 County or Parish	13 State
			Eddy	NM
	CK APPROPRIATE BOX(s) TO I	INDICATE NATURE OF NOTICE, REPO		
TYPE OS SUBMISSION		TYPE OF ACTI	ON	
✓ Notice of Intent	Acidize	·	ction (Start/Resume)	Water Shut-Off
Subsequent Report	Alter Casing Casing Repair		mation [nplete	Well Integrity Other
	Change Plans		orarily Abandon	
Final Abandonment Notice	Convert to Injection		· Disposal	
the Bond No on file with BLM/BIA Required su	ubsequent reports shall be filed within 30 days ng has been completed Final Abandonment	true vertical depths of all pertinent markers and zone s following completion of the involved operations. If the Notices shall be filed only after all requirement, inclu-	he operation results in a multiple co	mpletion or recompletion in a new
Devon Energy Production Company We are currently working on this wel		val to temporarily abandon this well whil abandonments	e we evaluate for a possibl	e plug and abandonment
We propose to TA this well per the f	ollowing procedure.	B	mrt	
1 MIRU PU. NU BOP		Approval for Subsequent requesting		
2 Unseat pump, pull and lay down rods and tubing			,	, ,
3 RIH with bit and scraper.		Subsequent	sundry re	eguirad
4 RIH with CIBP and set at 1827				
5 ND BOP RDMO PU		requesting	1H status	
6 Conduct mechanical integrity to	est.	<i>/</i> ~		
		SEE ATTACHED F	OR	
		CONDITIONS OF A	APPROVAL	
14 hereby certify that the foregoin	ig is true and correct		· · · · · · · · · · · · · · · · · · ·	<u></u>
Signed	7. Nam		Date	5/29/2007
	· · · · · · · · · · · · · · · · · · ·	or otal Engineering recrimician	Date	JILJILUUI

ACCEPTED FOR RECORD

Gerry Guyes Demoty Eidd Laspectorse Side NMOCD-District II ARTESIA Date

JUN 2 0 2007

WESLEYW. INGRAM
PETROLEUM ENGINEER

Title

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 505-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 505-361-2822; Lea County 505-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

WWI 11022006