

Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM
87505

Energy, Minerals and Natural Resources

May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-34235
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name 1724 Ross
8. Well Number 121
9. OGRID Number
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR - USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ **SEP 10 2007**

2. Name of Operator
LCX Energy LLC **OCD-ARTESIA**

3. Address of Operator
110 N. Marienfeld, Ste 200, Midland, Tx79701

4. Well Location
Unit Letter **O** **660** feet from the **South** line and **1880** feet from the **Esat** line
Section **12** Township **17S** Range **24E** NMPM County **Eddy**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,669' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type **Steel** Depth to Groundwater **210** Distance from nearest fresh water well **1000** Distance from nearest surface water **1000'**

Pit Liner Thickness: **nil** Below-Grade Tank: Volume **bbls** Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	CASING/CEMENT JOB ☐
	OTHER: ☐

13. Describe proposed or completed operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set C.I.B.P. @ 8,170', cap C.I.B.P. w/ 15 sx of cement, WOC, Tag.
2. Circulate hole w/ 9.5 # Salt Gel mud. (Displace all Plugs w/ 9.5# Salt Gel Mud)
3. Spot a 45 sx Plug 8170' - 8,000', Tag.
4. Spot a 85 sx Plug 7100' - 6300', Tag.
5. Spot a 85 sx Plug 6150' - 5350', Tag.
6. Spot a 25 sx Plug 3890' - 3790'
7. Spot a 25 sx Plug 3200' - 3100'
8. Spot a 55 sx Plug 1700' - 1300' - Tag
9. Spot a 45 sx Plug 600' - 330', Tag.
10. Spot a 25 sx Plug 30' - Surface. **60'**
11. Install Dry Hole Marker

**Notify OCD 24 hrs. prior
to any work done.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Howard Boatright TITLE Agent DATE 09/07/07
Type or print name Howard Boatright E-mail address: 432-617-0208
For State Use Only Telephone No.

APPROVED BY: Phil Hawkins TITLE Compliance Officer DATE Sept 11, 2007
Conditions of Approval (if any):

L C K
1724 Ross #121
Eddy Co NM

Before

13 3/8'
386

8 5/8'
1341'

5300-6105

6250-7050

7230-7970

8220-8910

5 1/2'
9020'

Note Cement
Circ on 8 5/8" Circ

Note Cement
Circ on 5 1/2" Cas

After P & F 60'

30ft - Surf 25' sx
Plus Dry Hole
marker

Spot a 45' sx
Ply. from 600-330
Tag

Tag
1700-1300 apt 55' sx

3200-3100 apt 25' sx

3890-3790 apt 25' sx

5350-6150
85' sx Tag

6300-7100
85' sx Ply Tag

8000-8170
45' sx Ply Tag

8170' + 1/2" = 8170'
CIBP