

## District I

1625 N. French Dr., Hobbs, NM 88240

## District II

1301 W. Grand Avenue, Artesia, NM 88210

## District III

1000 Rio Brazos Road, Aztec, NM 87410

## District IV

1220 S. St. Francis Dr., Santa Fe, NM 87501

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate

District Office in accordance

with Rule 116 on back

side of form

Oil Conservation Division

1120 South St. Francis Dr.

Santa Fe, NM 97505

30-015-28556

## Release Notification and Corrective Action

nmlb0726741031

873 OPERATOR



Initial Report



Final Report

Name of Company	Apache Corporation	Contact	Guinn Burks
Address	P. O. Box 728, Crane, TX 79731	Telephone No.	432-556-9143
Facility Name	Bright Federal Btty	Facility Type	Tank battery

Surface Owner	NM St.	Mineral Owner	BLM	API #	30-015-28556
---------------	--------	---------------	-----	-------	--------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	21	21	23E	1650'	South	1650'	West	Eddy

Latitude

Longitude

## NATURE OF RELEASE

Type of Release	Condensate	Volume of Release	45 bbls	Volume Recovered	45 bbls
Source of Release	Scrubber	Date/Hour of Occurrence	800 9-19-07	Date /Hour of Discovery	9/19/2007
Was Immediate Notice Given?		If Yes, To Whom?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		Left message for Mike Bratcher, contacted 9-21-07			
By Whom?		Date and Hour			
Guinn Burks		1450 9-21-07			
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					
If a Watercourse was Impacted, describe Fully*					
NA					
Describe Cause of Problem and Remedial Action Taken.*					
A cow rubbed on a pressure sensor and caused it to pull out of a victolic connection causing condensate to spill out into the berm.					
Describe Area Affected and Cleanup Action Taken.*					
This spill occurred inside a plastic lined berm and all spilled fluid was recovered and the gravel was washed down and that fluid was recovered with a vacuum truck as well. No damage to the environment was done.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature.	Oil Conservation Division TIM GUM by MB		
Printed Name:	Guinn Burks	Signed By <i>M. L. Bratcher</i>	
Title.	Permian Basin Environmental Tech.	Approved by the District Supervisor:	
Email Address:	guinn.burks@usa.apachecorp.com	Approval Date	SEP 24 2007
Date:	9/21/2007	Expiration Date:	N/A
Phone:	432-556-9143	Conditions of Approval:	N/A
		Attached	

\*Attach Additional Sheets if Necessary

2

Guinn,

Based on the information provided, the NMOCD will require no further action for this release at this time. The Form C-141 will be approved and imaged into the well file under the API number as listed.  
(30-015-28556)

Thank you,

Mike Bratcher  
NMOCD District 2  
1301 W. Grand Ave.  
Artesia, NM 88210  
(505) 748-1283 Ext. 108  
(505) 626-0857  
[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)

---

**From:** Burks, Guinn [<mailto:Guinn.Burks@usa.apachecorp.com>]  
**Sent:** Friday, September 21, 2007 3:52 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Trammell, Devalle; Ellison, Jim; Woolf, David  
**Subject:** C-141 for Bright Federal Btty Spill 9-19-07

Mike,

*Please find enclosed the required C-141 form for the above mentioned spill. As you will notice and remember from our phone conversation earlier today, this spill occurred inside a plastic lined berm and as such all fluid was recovered without damage to the environment. As stated from our conversation, this should be the only documentation required for this spill.*

*Your help in this matter, as always is greatly appreciated.*

*Guinn Burks*

*Permian Basin Environmental Tech.*

*Cell# 432-556-9143*

*Office# 432-558-3515*



---

This inbound email has been scanned by the MessageLabs Email Security System.

---

9/24/2007