

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
OMB No. 1004-0135  
Expires: January 31, 2004

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Mewbourne Oil Company 14744

3a. Address  
PO Box 5270 Hobbs, NM 88240

3b. Phone No. (Include area code)  
505-393-5905

4. Location of Well (Footage, Sec., T, R., M., or Survey Description)  
990' FNL & 1650' FEL, Unit B of Sec 12 -T21S-R27E


5. Lease Serial No.  
NM-17095  
6. If Indian, Allottee or Tribe Name  
7. If Unit or CA/Agreement, Name and/or No.  
32680  
8. Well Name and No.  
Esperanza 12 Federal Com #1  
9. API Well No.  
30-015-32935  
10. Field and Pool, or Exploratory Area  
Burton Flats Morrow  
11. County or Parish, State  
Eddy County NM

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>BOP Test</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

10/01/03... POOH @ 6953'. Test BOPE as required. All equipment passed.  
RIH & continue drilling operations.  
Chart & schematic enclosed. Drill out with 8 3/4" Bit.



14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

NM Young

Title Hobbs District Manager

Signature

Date 10/06/03

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by (Signature)

Name  
(Printed/Typed)

Title


Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.


Office

Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Continued on next page)






**(505) 396-4540**

INVOICE NO B-2253

Casing Valve Opened Yes Check Valve Open Yes



TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
1	1, 2, 6, 9, 13	10 min		3000	No Leaks
2	3, 4, 5, 10, 13	10		3000	
3	2, 5, 6, 5, 10, 13	10		3000	
4	7, 11, 12	10		3000	
5	7, 11, 12	10		3000	
6	7, 11, 15	10		1500	
7	17	10		3000	
					18 Did Not Hold. Replaced With New.

Mileage \_\_\_\_\_ @ \_\_\_\_\_

TOTAL 717.50

Mewbourne  
Esperanza 12 Feb, Com. #1  
Patt. UTL #47

Eddy, Co.

10-1-03

11" C-22

ASC Rev. 06-02

## Accumulator Function Test - OO&GO#2

### To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
  1. Open HCR Valve. (If applicable)
  2. Close annular.
  3. Close all pipe rams.
  4. Open one set of the pipe rams to simulate closing the blind ram.
  5. For 3 ram stacks, open the annular to achieve the 50±% safety factor. (5M and greater systems).
  6. Record remaining pressure 2100 psi. Test Fails if pressure is lower than required.
    - a. {950 psi for a 1500 psi system}
    - b. {1200 psi for a 2000 & 3000 psi system}
  7. If annular is closed, open it at this time and close HCR.

### To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
  - a. {800 psi for a 1500 psi system}
  - b. {1100 psi for 2000 and 3000 psi system}
  1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
  2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
  3. Record pressure drop 1000 psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system} b. {900 psi for a 2000 & 3000 psi system}

### To check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
  1. Open the HCR valve, {if applicable}
  2. Close annular.
  3. With pumps only, time how long it takes to regain the required manifold pressure.
  4. Record elapsed time 45 sec. Test fails if it takes over 2 minutes.
    - a. {950 psi for a 1500 psi system}
    - b. {1200 psi for a 2000 & 3000 psi system}

Accumulator working pressure rating	Minimum acceptable operating pressure	Desired precharge pressure	Maximum acceptable precharge pressure	Minimum acceptable precharge pressure
1,500 psi	1,500 psi	750 psi	800 psi	700 psi
2,000 psi	2,000 psi	1,000 psi	1,100 psi	900 psi
3,000 psi	3,000 psi	1,000 psi	1,100 psi	900 psi