UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.



FORM APPROVED OMB NO 1004-0135 Expires: July 31, 2010

Lease Serial No NMLC055561

6	If Indian	1 Allottee	or Tribe	Name

SUBMIT IN TRII	PLICATE - Other instruc	erse side.		7. If Unit or CA/Agree NM 109695X	ement, Name and/or	No			
1. Type of Well			8. Well Name and No. SOUTH RED LAK	T II I INIT 46	_				
Oil Well Gas Well Oth					E II OIVIT 40				
Name of Operator FAIRWAY RESOURCES OPE			9 API Well No. 30-015-25157						
3a. Address 538 SILICON DRIVE SUITE 1 SOUTHLAKE, TX 76092	3b. Phone No. (include area code) Ph: 817-416-1946 Ext: 220 Fx: 817-416-1949			10. Field and Pool, or Exploratory RED LAKE, QN, GB, SA					
4. Location of Well (Footage, Sec., T	, , , , , , , , , , , , , , , , , , ,		11. County or Parish, and State						
Sec 35 T17S R27E 1656FNL		.IAN 29 200)8	EDDY COUNTY COUNTY, NM					
			OCD_ARTE		<u> </u>				
12. CHECK APPF	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHEF	R DATA			
TYPE OF SUBMISSION	,		F ACTION		i				
Notice of Intent	☐ Acidize	□ Deep	oen	□ Product	ion (Start/Resume)	□ Water Shut-C	Off		
_	☐ Alter Casing	□ Frac	☐ Fracture Treat		ation	□ Well Integrity	y		
☐ Subsequent Report	☐ Casing Repair	☐ Casing Repair ☐ New Construction ☐		. Recomp	olete	□ Other			
Final Abandonment Notice	Change Plans	⊠ Plug	and Abandon	□ Tempor	arily Abandon				
	Convert to Injection	□ Plug	Back	□ Water I	Disposal				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Spud 1-31-1983 TD 1803' PBTD 1733' 8 5/8" 24# casing set at 450', cement circulated to surface 5 1/2" 17#N-80 casing set at 1803', cement circulated to surface 1/2008 - CIPB set at 1510' with 10' of cement on top Proposed work: 25 5x plug or 35"; f 55 will dump ba; ler # TIH with tubing and spot 50' cement-plug-on top of CIBP at 1510'. Tag plug and circulate abandonment mud. Spot 100' cement plug (25 sack minimum) at 400' - 500' with tubing.									
Tag plug and circulate abando	onment mud.			APPR	OVED				
14 Thereby certify that the foregoing is	by the BLM Wel	II Information t to the Carls	bald ////	2 / 2008					
Name (Printed/Typed) KENNETH	Title ENGINEER JAMES A. AMS SUPERVISOR-I		A. AMOS						
Signature (Electronic S	Date 01/24/2								
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE				
Approved By	Title Accepted for recordate								
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condition									
Title 18 U S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	a crime for any p s to any matter w	erson knowingly as	nd willfully to 1	nake to any department	or agency of the Unit	ted		

Additional data for EC transaction #58256 that would not fit on the form

32. Additional remarks, continued

Spot 100' cement plug (25 sack minimum) at surface. Install dry hole marker Clean and remediate location.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.