

N.M. Oil Cons. DIV-Dist. 2

UNITED STATES 1301 W. Grand Avenue DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTS 18, NM 882 The case Serial No.

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

NM-87187

SUNDRY N	NOTICES AND REPORTS ON WELLS
Do not use this f	form for proposals to drill or to re-enter an
	III- F 0400 0 (4 DD) for such approach

SUNDRY NUTICES AND REPORTS ON			
Do not use this form for proposals to drill or table abandoned well. Use Form 3160-3 (APD) for su			
SUBMIT IN TRIPLICATE - Other instructions	on page 2. 7. If Unit of CA/Agreement, Name and/or No.		
. Type of Well	FEB 1 5 2008 8 Well Name and No.		
Oil Well Gas Well X Other	Indian Creek Federal # 1		
Name of Operator Medallion Oil Company	9. API Well No. 30\$-035-20030		
	o. (include area code) 10. Field and Pool or Exploratory Area		
	-654-0144 Abo Wildcat 11. Country or Parish, State		
Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1800' FSL, 2285' FEL, Unit J, Sec 14. T	23S, N.M.P.M. Otero County, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION ACCEPTED FOR PROCESS		
Notice of Intent	pen Production (Start/Resume) Water Shut-Off		
	reture Treat Reclamation Well Integrity Construction Recomplete Char 2000		
Subsequent Report	Recomplete Temporarily Abandon Temporarily Abandon		
	Back		
All subsurface details of Plugging & Abandonment were provided on subsequent Sundry Notice dated March 15, 2000, a copy of which is attached. All drill cuttings were confined and hauled to waste disposal immediately after the subsurface plugging was completed The suface location was restored and initially seeded by Sweatt Construction, Inc, of Artesia during April and June, 2000. Medallion Oil/Sweatt Construction then reseeded the site in January, 2001 and reported same to Medallion on February 5, 2001 via letter (See attached). The Forest Service reported on October 18, 2001 the location was disturbed and partially dredged after Medallion Oil Company-Sweatt Construction had seeded the location. On October 19, 2001, after discussing the status of the site restoration with Mr. Larry Paul of the Forest Service, he indicated that he would write a letter releasing Medallion on the surface restoration.			
4. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Donald R. McLelland	Title Vice President, Engineering and Operations		
Signature Would P. Whe Telland	Date January 14, 2008		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
s			

Instructions on page 2)