

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an  
abandoned well. Use Form 3160-3 (APD) for such proposals.*



**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

**Pogo Producing Company**

3a. Address

**P. O. Box 10340, Midland, TX 79702**

3b. Phone No. (include area code)

**432-617-0208**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**1980 FNL, 1980 FEL  
G-Sec. 12, T22S, R31E**

FEB 21 2008

OCD-ARTESIA

5. Lease Serial No.

**NM-12845**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No

**SCL Federal #2**

9. API Well No.

**30-015-24232**

10. Field and Pool, or Exploratory Area

**Red Tank, Atoka**

11. County or Parish, State

**Eddy County NM**

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamantion	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

**1/16/08-1/17/08 MIRU plugging company. ND wellhead and NU BOP.**

**1/18/08-1/19/08 RIH w/ tbg. worked on rig. 1/22/08 Tagged CIBP @ 13545. Spot 25sx cement on top. POH w/ 57 jts. tbg. 1/23/08 circulated hole w/ mud laden fluid. Spot 35 sx. plug @ 11720. 1/24/08 WIH and tagged plug @ 11359'. POH w 79 jts. tbg. Spot 45 sx cement plug @ 9180-8950'. POH to 8050'. Spot 45 sx. cement plug @ 8050-7820. POH w/ tbg. 1/25/08 RIH w/ 7 5/8 packer and 160 jts. tbg. 1/28/08 RIH w/ 20 jts. tbg. set packer @ 5921'. RIH w/ wireline and perf. csg @ 6200'. Sqz. 65 sx cement. Close well in. 1/30/08 Release packer. Laid down 51 jts. tbg. RIH w/ WL and perf. 7 5/8 csg. @ 4584'. Set packer @ 4279'. Sqz. 65 sx cement. WOC 4 hrs. Unset packer. Laid down 26 jts. tbg. 1/31/08 RIH w/ WL and tag plug @ 4429'. POH. RIH and Perf. csg. @ 3784'. Set packer @ 3443'. Sqz. 65 sx. cement. WOC 4 hrs. Tag plug @ 3632'. Perf. csg. @ 2780'. Set packer @ 2413. Sqz. 65 sx cement. WOC overnight. 2/01/08 Tag plug @ 2584'. POH w/ WL. Laid down 75 jts. tbg. Perf. csg. @ 800'. Set packer @ 514'. Sqz. 100 sx cement. WOC 4 hrs. Tagged plug @ 676'. POH w/ packer. Perf. csg. @ 100'. Set packer at 30'. Sqz. and circulate cement to surface. 2/04/08. POH w/ packer. Spot 45 sx. cement from 100' to surface. Cut off wellhead and weld on Dry Hole Marker. Rigged down.**

14. I hereby certify that the foregoing is true and correct.)

Name (Printed/Typed)

Title

Signature

Date

2-7-2008

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

**ACCEPTED FOR RECORD**

Approved by

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title

Office

Date

FEB 15 2008

Title 18 U.S.C. Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE**