## **UNITED STATES** OCD-ARTESIA

DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

BUREAU OF LAND MANAGEMENT

FEB 26 200 5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS NM-83584 Do not use this form for proposals to drill or to re-enter an OCD-ARTES NM-83584
6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals.

				-						
	IPLIC	ATE - Other instru	ctions on	reve	rse side	) Personal	7. If Unit o	or CA	Agreement, Name and/or No.	
1. Type of Well	•									
Oil Well Gas Well Other							8. Well Name and No.			
Name of Operator     Mewbourne Oil Company 14744							Federal V #3  9. API Well No.			
								30-015-26867		
								10. Field and Pool, or Exploratory Area		
PO Box 5270 Hobbs, NM 88240 505-393-59  4. Location of Well (Footage, Sec., T, R., M., or Survey Description)							Undesign			
1980' FNL & 660' FWL, Unit Letter E of Sec 8-T20S-R28E							11. County	11. County or Parish, State		
						Eddy County, NM				
12. CHECK AP	PROP	RIATE BOX(ES) TO	INDICAT	E NAT	TURE O	F NOTICE,	REPORT, O	R O	THER DATA	
TYPE OF SUBMISSION TYPE OF ACTION										
✓ Notice of Intent	000	Acidize Alter Casing	Deepen Fracture Treat			Production (Sta Reclamation	rt/Resume) [	000	Water Shut-Off Well Integrity	
Subsequent Report	냄	Casing Repair	New Cor		=	Recomplete		ч	Other	
Final Abandonment Notice		Change Plans Convert to Injection	✓ Plug and □ Plug Bac		" <u> </u>	Temporarily A Water Disposal				
Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready  MOC has tested the above caption of the investing has been completed. Find determined that the site is ready  MOC has tested the above caption of the investigation of the second of the investigation of the investiga	Duming 59(ge. csg th	perations. If the operation r ndonment Notices shall be all inspection.)  in the Queens Sands @ 1 p bail 35' cmt on CIBP @ Queens Perfs @ 1,080' - 1 n CIBP @ 1,060'.  )').  uru holes @ 580' & up 8 december 1 as required.	esults in a m filed only aft 1,080' - 1,09 2,698'. ,098').	ultiple co er all rec 8' & wo	ompletion quirements	or recompletions, including recl	ell as follows:	P FE	PROVED	
14. 1 hereby certify that the foregoing is true and correct Name (PrintedlTyped)						SFF AT	SEE ATTACHED FOR			
Levi Jackson				litle	Title Engineer		CONDITIONS ST			
Signature Date						CONDITIONS OF APPROVAL				
		THIS SPACE FO	)R PEDER	ALOR	STATE	OFFICE US	Ë			
Approved by (Signature)					Name (Printed/Typed) Ti			Title		
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon									Date	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.