Form 3160-5 (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

FEB 2 1 2008 OCD-ARTESIA EXPIRES

EORM APPOVED

FURIV	IAFROVED
OMB N	O. 1004-0135
EXPIRES:	March 31, 200

Do not use this form for proposals to drill or to re-enter an			NM 81953 6. If Indian, Allottee or Tribe Name				
abandoned well. Use Form 3160-3 (APD) for such proposals  SUBMIT IN TRIPLICATE				o. Il fildiali, Allottee	of Tribe Name		
SUBMIT IN TRIPLICATE				Unit or CA Agreement Name and No.			
1a. Type of Well Oil Well Gas Well Other			8 Well Name and No.				
2. Name of Operator			North Pure Gold 5 Federal 2H				
DEVON ENERGY PRODUCTION COMPANY, LP			9. API Well No.				
3. Address and Telephone No.				30-015-35850			
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611				10. Field and Pool, or Exploratory			
4. Location of Well (Report location clearly and in accordance with Federal requirements)* 150' FNL 1980' FEL Unit B SEC 5 T23S R31E			Los Medanos; Delaware  11. County or Parish State				
BHL:330' FSL 1980' FEL	PP: 16	9' FNL & 1962' FEL		Eddy	NM		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OS SUBMISSION		TYF	PE OF ACTION				
☐ Notice of Intent	Acidize Alter Casing	☐ Deepen ☐ Fracture Treat	Productio Reclamat	n (Start/Resume) ion	☐ Water Shut-Off ☐ Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomple		Other Completion		
☐ Final Abandonment Notice	☐ Change Plans☐ Convert to Injection	Plug and Abandon Plug Back	= '	mporarily Abandon Report ater Disposal			
Interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  12/13/07 - 1/10/08 MIRU Key Well ServiceE RIG #168. NU BOP. PBTD @ 12,337'. Test csg to 4500#. CHC w/ KCL wtr. Perf toe section 10530-32'; 11130-32'; 11728-30' & 12330-32' @ 5 spf: total 40 shots. RU BJ Services pump 500 g pickle acid to EOT. Spot 1200 g 7 1/2% NEFE acid from 12338'-10350'. Test to 7000#. Acidize w/ 4000 g 7 1/2% NEFE acid w/ 80 BS. FL w/ KCL wtr. ND BOP. Test to 1000#. Frac L. Brushy Canyon perfs 10530'-12332' w/ 306,040 g Spectra Star 2800 Gel, 12,500# 100 mesh sd, 371,020# 20/40 white sd & 111,055# 16/30 Siberporp sd. FL w/ 13,902 g 10# gel. Pump 220 g Baker Technihib Scale Inhibitor. RD frac crew. ND frac head & NU BOP. Pump 30 bbls KCL wtr. CHC. RU Baker Atlas & BJ. Ran CBP into liner & pump 156 bbls KCL dn to 10,300' & set CBP. Test to 1250#, ok. RD WL & PT. RU Baker Atlas & perf heel sec of Brushy Canyon 8125-27'; 8729-31'; 9327-29'; 9929-31' @ 5 spf: total 40 shots. RU BJ. Set pkr @ 9984'. Test to 4000#. TOOH w/ pkr. RIH w/ CBP to 10264'. RU BJ. & acidize heel section 8125-9931'. Spot 1200 g 7 1/2% HCL across perfs. Acidize w/ 4000 gals & 1/2% HCL acid & 80 BS. FL w/ KCL wtr. ND BOP. Frac w/ 4620 g Spectra Star 2800 gel, 400# 100 mesh sd & 23,500 g KCL wtr. RU BJ. & frac w/ 311,178 g Spectra Star 2800 Gel, 12,500# 100 mesh sd, 370,920# 20/40 white sd & 110,003# 16/30 Siberprop sd. FL w/ 12,054 g 10# gel. Pump 220 g Baker Technihib Scale Inhibitor. RD frac crew. CHC. DO CBP @ 10,264'. ND frac valve. NU BOP. CHC w/ KCL wtr. NU WH for sub pump. RDMO. POP.							
14. I hereby certify that the foregoing is	true and correct						
Signed Jud CK	Name Title	Judy A. Barnett Regulatory Ar		Date	2/20/2008		
(This space for Federal or State Office us	se)						
Approved by Conditions of approval, if any:	Title			Date			

This to 0.5.C. Section 1001, makes it a crime for any person knowingry and williumy to make any department or agency or the officer States any faise, rictious or fraudulent statements or representations to any matter within its jurisdiction