

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-34390
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-0730
7. Lease Name or Unit Agreement Name Top Dollar State Com
8. Well Number 1
9. OGRID Number 14049
10. Pool name or Wildcat Hackberry; Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ **JUN 25 2008**

2. Name of Operator **OCD-ARTESIA**
Marbob Energy Corporation

3. Address of Operator
PO Box 227, Artesia, NM 88211-0227

4. Well Location
Unit Letter O : 990 feet from the South line and 1980 feet from the East line
Section 16 Township 19S Range 31E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3488' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plugged and abandoned as follows:

5/19/08 – Set CIBP + 35' cmt @ 4200'. Circ w/ 137 bbls 9 ppg plug mud. Pull up to 2905'. Spot 30 sx Class "C" neat cmt across 9 5/8" shoe @ 3860'. WOC 2 hrs. Tag @ 3726'. Set CIBP @ 2213'. Circ 100 bbls 9 ppg plug mud. Set CIBP @ 2051'. Pump 140 sx Class "C" neat cmt.
5/20/08 – Perf 4 holes @ 760'. RIH to 764'. Spot 100 sx Class "C" neat cmt from 490' – 760'. WOC 1 1/2 hrs. Tag cmt @ 455'. Perf 4 holes @ 60'. RIH to 64.40'. Pump cmt up 9 5/8" & 5 1/2" csg to surface. Top off well.
5/26/08 – Cut off well head & anchors. Install dry hole marker per OCD specs.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Briggs TITLE Production Analyst DATE 6/25/08

Type or print name Diana J. Briggs E-mail address: production@marbob.com PHONE: (575) 748-3303

For State Use Only

APPROVED BY: NMOCD TITLE

Conditions of Approval (if any):

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms. www.emnrd.state.nm.us/oed.

DATE 6/25/08