## **UNITED STATES** DEPARTMENT OF THE INTERIOR

OCD-ARTESI

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

and a

BUREAU OF LAND MANAGEMENT

5 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an			069	641	
			6 If Indian. Allottee or Tri	be Name	
abandoned	well. Use Form 3160	-3 (APD) for such p	roposals.		
SUBMIT IN TRIPLICATE – Other instructions on reverse side			7 If Unit or CA/Agreemer	it. Name and/or No	
1 Type of Well		J);	N 2 4 2008	8 Well Name and No	-
Oil Well Gas Well Gother		_	romion Unit D #5		
Nordstrand Engineering Inc.  OCD-ARTESIA			West Henshaw Premier Unit P #5 9 API Well No		
3a Address 3b Phone No (include area code)			30-043	-03844	
3229D'Amico St. #2200, Ho				10 Field and Pool, or Exp	loratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				w Grayburg	
UL W, Sec 3-16S- 30E 990 FSL, 2310 FEL			11 County or Parish, State		
	PROPRIATE BOX(F)	S) TO INDICATE NA	TURE OF NOTICE, RE	PORT OR OTHER DA	The state of the s
TYPE OF SUBMISSION	TROTALLE BOX(E)	s) TO INDICATE IV	TYPE OF ACTION	TORT, OR OTHER DE	
THE OF SEDIMODION	Acidize	Deepen	Production (Start/Resum	ne) Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Subsequent Report	Change Plans	Plug and Abandon	Temporarily Abandon	C Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	4.500	
13. Describe Proposed or Completed				ny proposad work and appr	no imate duration thereof
OH 2867-2909  1. MIRU plugging company 2. RIH w/ 5 1/2 CIBP and s 3. Perf. 5 1/2 csg @ 2200' S 4. Perf. 5 1/2 csg. @ 1500' S 5. Perf. 5 1/2 csg. @ 600'. S 6. Spot 10 sx surface plug. G	et @ 2825. Circulat et packer @ 2000'. Set packer @ 1300. et packer @ 400. So Cut off wellhead an	Sqz. 50 sx. cement. Sqz. 50 sx cement. qz. 50 sx. cement. V d weld on Dry Hol	WOC and Tag. @ WOC and Tag. @ WOC and Tag. @ e Marker. Aerf	2080, min 1380, min 2 60' cine plug SEE ATTAI	CHED FOR
				CONDITIO	NS OF APPROVAL
14 I hereby certify that the foregoing is	true and correct.)	1			
Name (Printed/Typed) Roger Brooks		Tul	e Agent		
1000 180	2 /2 .				501/55
Signature Roger Brooks Date 6/16/08  THIS SPACE FOR FEDERAL OR STATE OFFICE U		APP APP	KOVED		
		FUR FEDERAL	UK STATE OFFICE	USE	
Approved by ACCEPTED	for record	٤	Title .	Date JUN	2 1 2008
Conditions of approval, if any, and the applicant holds legal or equitable and	o Ap I wal of this notice do	nes not warrant or certify that lease which would entitle the			
applicant to conduct operations thereon.			f": "·	JAME	S A. AMOS
Title 18 U S C. Section 1001 and Title 43 States any false, fictitious or fraudulent's	5 U.S.C. Section 1212, make tatements or representations;	it a crime for any person kni is to any matter within its ju	owingly-and willfully to make to risdiction	any department or agoncy of	S A. AMOS RVISOR-EPS

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Accepted for record NMOCD