District I

State of New Mexico Energy, Minerals and Natural Resources Form C-103 May 27, 2004

WELL API NO.	
30-015-31543	
5. Indicate Type of Lease	
CTATE .	CEE 🗆

District II OIL CONCEDIATION DIVISION	30-015-31543
1301 W Grand Ave., Artesia, NM 88210 1302 Courtle St. Francia Dr.	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE 🔀 FEE 🗆
District IV	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	o. State off & das Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Win 29 STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other JUN 2 0 2008	1
12. Name of Operator	9. OGRID Number
SDX RESOURCES INC. OCD-ARTESIA	020451
3. Address of Operator	10. Pool name or Wildcat
P.O. BOX 5061 MIDLAND TEXAS 79704	UNDESMILLMAN YT -7R-ON.EAST
4. Well Location	
Unit Letter P: 330 feet from the SOUTH line and	990 feet from the EAST line
Section 29 Township 19S Range 28E	
11. Elevation (Show whether DR, RKB, RT, GR, 3367' Gr	etc.)
Pit or Below-grade Tank Application or Closure	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well I	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construc	tion Material
See	
12. Check Appropriate Box to Indicate Nature of Notice	Donast on Othon Data
	•
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🗌 REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	LING OPNS. DPLUG AND ABÁNDONMENT
PULL OR ALTER CASING	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-4-08 MIRU BASIC RIG 1273 6-4-08 TIH OE & TAG CIBP @ 1430 6-4-08 SPOT 25 SXS CMT CALCULATE TOC @ 1180 6-4-08 PULL TBG TO 428' 50' BELOW SURFACE SHOE MIX & CIRCULATE OMT TO SURFACE W/ 50 SXS OMT. LAY DOWN TBG & TOP WELL OFF. 6-5-08 CHECK PLUG @ SURFACE RIG DOWN MOVE OFF LOCATION

OTHER:

WELL WAS CIRCULATED W/ 10 # MLF

WILL CUT ANCHORS & INSTALL DRY HOLE MARKER ASAP

PHIL HAWKINS NMOOD p7A PROCEDURE

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further cer	tify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternated of the second o	tive OCD-approved plan
Bandell M	
SIGNATURE DOWN WILL TITLE D	ATE.

Type or print name

OTHER:

For State Use Only

APPROVED BY

Conditions of Approval, if any:

Accepted for record

NMOCD

TITLE

Approved for plugging of well bore offelephone No. Liability under bond is retained pending receipt of C.103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under

Forms, www.cmnrd.state.nm.us/ocd.