Submit 2 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		October 25, 2007 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II			30-015-26431
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> 1000 Rio Biazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Dagger Draw 31 Federal
PROPOSALS.)			8. Well Number 2
1. Type of Well: Oil Well Gas Well Other			
Name of Operator     Nearburg Producing Company		9. OGRID Number 015742	
3. Address of Operator		10. Pool name or Wildcat	
3300 N A St., Bldg 2, Ste 120, Midland, TX 79705			Dagger Draw; Upper Penn, North
4. Well Location			
Unit Letter B: 660 feet from the North line and 1930 feet from the East line			
Section 31 Township 19S Range 25E NMPM County Eddy			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:  K
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			———————————————————————————————————————
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
OTHER.   Location is ready for OCD inspection after P&A  All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
Archors, dead men, the downs and risers have been cut off at least two feet below ground level.  If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)  All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from			
non-retrieved flow lines and pipelines.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.			
inspection has to be made to a Text location occause it does not meet the eriteria above, a penalty may be assessed.			
SIGNATURE / JOSO	M TITLE !	Production Analyst	DATE6/6/08
			g.com PHONE: _432/686-8235
APPROVED BY: Conditions of Approval (if anv):  ACCEPTED for record TITLE  DATE 7/16/88			
APPROVED BY:	ed for record TITLE		DATE 7//6/68
Conditions of Approval (if anv):	MOCD		
	~ ~ ~		•