Subutit 3 Copies To Appropriate District	State of New Mexico		Form C-103		
Office <u>District !</u> 1625 N Flench Dr , Hobbs, NM #8240	Energy, Minerals and Natural Resources		WELL API NO.		
District 11 1301 W. Grand Ave , Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		30-015-33978		
Diatrici III			5. Indicate Type of Lease STATE  FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV			6. State Oil & Gas Lease No.		
1220 S St Francis Dr., Santa Fe, NM 87505			V-7113		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			San Juan State Com		
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well 🛛 Other		8. Well Number 1		
2. Name of Operator Mack En	Name of Operator Mack Energy Corporation			9. OGRID Number 013837	
3. Address of Operator			I 0. Pool name or Wildcat		
P. O. Box 960 Artesia, NM 88211-0960			Penasco Draw;Permo Penn		
4 Well Location	660 feet from the	South line and	660 feet from the	e East line	
Unit Letter P Section 17	660feet from the Township 18S	Range 24E		e East line ounty Eddy	
Scotlett	11. Elevation (Show whether			unty	
3764' GR					
Pit typeDepth GroundwaterDistance from nearest fresh water wellDistance from nearest surface water					
Pit Liner Thickness:mi  Below-Grade Tank: Volumehhls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF I	NTENTION TO:	l SUB	SEQUENT REPOR	RT OF∙	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		_	ERING CASING [	
TEMPORARILY ABANDON		COMMENCE DR		ND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	т ЈОВ 🔲		
OTHER:		OTHER:	****		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
REVISED 10/1/08					
Notify OCD 24 hours prior to starting plugging operations					
1) Set CTBP @ 6100' w/35' cmt cap. 7" casing @ 6155'.					
2) Set 25sx cmt plug at 5000' (Wolfcamp) 3) Set 25sx cmt plug @ 3700' (Abo)					
4) RIH found TOC @ 2800', cut 7" 23# J-55 csg. and POH. Per Mike Bratcher set plug 50' above and below csg cut point					
2800-2700' (tag)					
5) Set 25sx plug from 1260-1160'. (tag) 6) Set 30sx cmt plug from 90' to surface,					
7) Install P & A Marker.	411400,				
Notes 15 Office and Health and a 1	4				
Note: 1) Circ. well with salt gel mud consisting of at least 9.5# Brine with 25 pounds of gel per barrel after the bottom plug is set.					
<b>6 f</b>	P8				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be-constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE Leny W.	/ 1 A	LE Production Clerk		TE 10/1/08	
Type or print name Jerry W. Sherr		l address: jerrys@macker		none No. (575)748-1288	
For State Use Only			тысрі	TOTAL TRUIT	
APPROVED BY: Miles Desay	War TITI	IE Dura I	T	TE 10/1/08	
Conditions of Approval (if any)	111	LE MARGON WISKE	DA	10 10/1/08	