

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

DUPLICATE

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30.015.22804

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Empire Abo Unit "E"

8. Well Number
363

9. OGRID Number
000778

10. Pool name or Wildcat
Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
BP America Production Company

3. Address of Operator
P.O. Box 1089, Eunice, NM 88231

4. Well Location

Unit Letter A : 650 feet from the N line and 120 feet from the E line

Section 34 Township 17S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3673.5' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6350' PBD: 6025' PERFS: 5860-5978

09.03.03: MIRUPU. NDWH. NUBOP. POH.

09.04.03: RIH testing tbg in hole. Tag BP @ 5963'. Could not unlock BP. POH

09.05.03: Change retrieving tool. RIH and unset plug. POH.

09.08.03: RIH w/bit & scraper. Tag @ 6059'.

09.09.03: RU wireline. RIH w/CIBP. Set @ 6025'. Dump 10' cmt on top of plug. Log well.

09.10.03: RIH w/perf guns. Perf well 5860-64', 5886-89', 5914-16', 5920-22', 5940-42', 5949-51', 5958-60', 5965-67', 5970-71', 5974-76', 5978'. 66 holes, 2 JSPF. RIH w/pkr.

09.11.03: Set pkr 20 jts. above perfs. Rig up and spot scid @ 5990'. Follow acid w/12 bbls KCL. POOH 7 jts. Set pkr @ 5777'. Pmp 1700 gals 15% HCL acid dropping 100 ball sealers. Flush w/ 27 bbls KCL. Unset pkr POH.

09.12.03: RIH w/bailer and CO. Tag at 6035'. POH.

09.15.03: RIH w/prod. Tbg. Set @ 5947'. NDBOP. NUWH. RTP. In 24 hrs. pmp'd 0 BO, 2 BW, 10 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Admin. Asst. DATE 10.06.03

Type or print name Kellie D. Murrish E-mail address: murrikd@bp.com Telephone No. 505.394.1649

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE DATE OCT 29 2003
Conditions of approval, if any: