Submit 3 Copies To Appropriate District Office District I

State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised May 08, 2003

1625 N. French Dr., 1	Hobbs, NM 8724	0					WELL AI		0.0	-
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVIS							30.015.22786 5. Indicate Type of Lease			
District III 1220 South St. France						l	· · · —	_		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV								ATE X	FEE 📙	\dashv
1220 S. St. Francis D	r., Santa Fe, NM	87505					6. State C	Oil & Gas Lea	se No.	
	SUNDRY N	OTIC	ES AND REP	ORTS ON	WEL	LS	7. Lease	Name or Unit	Agreement Name:	一
(DO NOT USE THIS	S FORM FOR F	PROPO	SALS TO DRILL	OR TO DEE	PEN C	OR PLUG BACK TO A		Abo Unit "F		ı
DIFFERENT RESE PROPOSALS.)	RVOIR. USE "A	APPLIC	ATION FOR PE	RMIT" (FOR!	VI C-10	1) FOR SUCH	_			
1. Type of Well:						2242528222	8. Well N	o.		
Oil Well 🗶			Other		18	Reservation of the second		376		
2. Name of Oper	ator				202,	nor.	9. OGRII	Number		
BP America	Production	Comp	any		702	00/2003		000778		
3. Address of Op	perator				3.10	OCD ADTED		name or Wild	cat	
	089 Eunice	NIM 8	8231		\\(\overline{\pi_2}\)	ARTESIA	Empire 1	Apo		_
4. Well Location					ي الم	CO12				
Unit Letter	E	:	1335 feet	from the	N	Line and	700	feet from the	e W lii	ne
						51017273				
Section	35			nship 17		Range 28E	NMPM	C	ounty Eddy	200
			11. Elevation	n (Show wh		DR, RKB, RT, GR, et 5.3' GR	c.)			
100000000000000000000000000000000000000	12 Che	eck A	nnronriate F	Box to Ind		Nature of Notice,	Report (or Other Da) 11/2	OOC
NC			ENTION TO		iicaic	· ·	-			
					_		SEQUE	NT REPOF		_
PERFORM REME	DIAL WORK	Ш	PLUG AND A	ABANDON		REMEDIAL WORK		<u></u> А	LTERING CASING	
TEMPORARILY A	BANDON		CHANGE PL	ANS		COMMENCE DRILLI	NG OPNS.	□ P A	LUG AND BANDONMENT	
PULL OR ALTER	CASING		MULTIPLE			CASING TEST AND				
			COMPLETIC	ON		CEMENT JOB				
OTHER:						OTHER: MIT				x
	onosed or co	mnlete	ed operations	(Clearly sta	ate all		vive pertine	nt dates inclu	ding estimated date	
13. Describe pro						pertinent details, and g				
13. Describe pro of starting ar	ny proposed w									
13. Describe pro	ny proposed w ion.	ork).	SEE RULE 1	103. For M	lultiple	pertinent details, and ge Completions: Attach				
13. Describe pro of starting ar	ny proposed within	ork).		103. For M	lultiple	pertinent details, and g				
13. Describe proof starting ar or recomplet TD: 6357	ny proposed with the proposed	ork). 85' C	SEE RULE 1	103. For M	iultiple S: 5	pertinent details, and ge Completions: Attach	wellbore d	iagram of pro		
13. Describe proof starting ar or recomplet TD: 6357	ny proposed with	vork). 85' C	SEE RULE 1	103. For M 79' PERF:	iultiple S: 5 Held	pertinent details, and ge Completions: Attach	wellbore d	iagram of pro		
13. Describe proof starting ar or recomplet TD: 6357	ny proposed with	vork). 85' C	SEE RULE 1	103. For M 79' PERF:	iultiple S: 5 Held	pertinent details, and ge Completions: Attach	wellbore d	iagram of pro		
13. Describe proof starting ar or recomplet TD: 6357	proposed with pr	vork). 85' C Sest c Suy, N	SEE RULE 1 TIBP: 5982.	103. For M 79' PERF: 0# psi. 1 t attached	ultipk S: 5 Held d.	pertinent details, and ge Completions: Attach	wellbore d	iagram of pro		
13. Describe proof starting ar or recomplet TD: 6357	proposed with pr	vork). 35' C cest c My, N	SEE RULE 1 TIBP: 5982. Tasing to 55 TMOCD. Char	103. For M 79' PERF: 0# psi. 1 t attached	ultipk S: 5 Held d. valua	pertinent details, and ge Completions: Attach	est witne	iagram of pro essed determined	posed completion	
13. Describe proof starting ar or recomplet TD: 6357	PED: 603 Load and t by Gerry G BP America that these	cest coly, No.	SEE RULE 1 TBP: 5982. casing to 550 MOCD. Char duction Componeduction purefere req	79' PERF: 0# psi. I t attached any has enotential: uested in	ultiple S: 5 Held d. valua in th	pertinent details, and get Completions: Attachers 994-6002' 30 mins. Casing to ted this wellbore a Abo formation.	est witne	essed determined on to retain	posed completion	
13. Describe proof starting ar or recomplet TD: 6357	PED: 603 Load and t by Gerry G BP America that these	cest coly, No.	SEE RULE 1 TBP: 5982. casing to 550 MOCD. Char duction Componeduction purefere req	79' PERF: 0# psi. I t attached any has enotential: uested in	ultiple S: 5 Held d. valua in th	pertinent details, and ge Completions: Attache 994-6002' 30 mins. Casing ted this wellbore a Abo formation.	est witne	essed determined on to retain	posed completion	
13. Describe proof starting ar or recomplet TD: 6357	PED: 603 Load and t by Gerry G BP America that these	cest of Aug. No. 1 Process is the property and the process of the	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction potential regions required to the control of the control	79' PERF: 0# psi. I t attached any has enotential: uested in	ultiple S: 5 Held d. valua in th	pertinent details, and get Completions: Attachers 994-6002' 30 mins. Casing to ted this wellbore a Abo formation.	est witne	essed determined on to retain	posed completion	
13. Describe proof starting ar or recomplet TD: 6357	proposed with pr	cest of Aug. No. 1 Process is the property and the process of the	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction potential regions required to the control of the control	79' PERF: 0# psi. I t attached any has enotential: uested in	ultiple S: 5 Held d. valua in th	pertinent details, and get Completions: Attachers 994-6002' 30 mins. Casing to ted this wellbore a Abo formation.	est witne	essed determined on to retain	posed completion	
13. Describe proof starting ar or recomplet TD: 6357	proposed with pr	cest of Aug. No. 1 Process is the property and the process of the	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction potential regions required to the control of the control	79' PERF: 0# psi. I t attached any has enotential: uested in	ultiple S: 5 Held d. valua in th	pertinent details, and get Completions: Attachers 994-6002' 30 mins. Casing to ted this wellbore a Abo formation.	est witne	essed determined on to retain	posed completion	
13. Describe proof starting are or recompleted. TD: 6357' 10.15.03:	PBD: 603 Load and t by Gerry 6 BP America that these TA status and develo	west coars, No. 2007. Proces is the process and another second in the process of	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction purefore requirements of the control of th	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and get Completions: Attachers 294-6002' 30 mins. Casing the ted this wellbore a Abo formation. The complete our che will require in the complete our check the com	and has correct v	essed determined on to retain	posed completion	
13. Describe proof starting are or recompleted. TD: 6357' 10.15.03:	PBD: 603 Load and t by Gerry 6 BP America that these TA status and develo	west coars, No. 2007. Proces is the process and another second in the process of	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction purefore requirements of the control of th	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and get Completions: Attachers 994-6002' 30 mins. Casing to ted this wellbore a Abo formation.	and has correct v	essed determined on to retain	posed completion	
13. Describe proof starting are or recompleted. TD: 6357 10.15.03:	PBD: 603 Load and t by Gerry 6 BP America that these TA status and develo	west coars, No. 2007. Proces is the process and another second in the process of	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction purefore requirements of the control of th	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and ge Completions: Attache 294-6002' 30 mins. Casing to ted this wellbore a Abo formation. The to complete our che will require in the complete our check the check the check the check the complete our check the check t	and has corrent values of	essed determined on to retain workover pro	n ogram al to	
13. Describe proof starting are or recompleted. TD: 6357' 10.15.03:	PBD: 603 Load and t by Gerry 6 BP America that these TA status and develo	west coars, No. 2007. Proces is the process and another second in the process of	SEE RULE 1 TEP: 5982. Tasing to 55 MOCD. Char Auction Componeduction purefore requirements of the control of th	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and ge Completions: Attache 294-6002' 30 mins. Casing to ted this wellbore a Abo formation. The to complete our che will require in the complete our check the check the check the check the complete our check the check t	and has correct v	essed determined on to retain workover pro	posed completion	
13. Describe proof starting are or recompleted. TD: 6357 10.15.03:	PED: 603 Load and to by Gerry	est carry, Na Process	SEE RULE 1 CIBP: 5982. Casing to 55 MOCD. Char Chection Componeduction perefore requirements of the control	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and ge Completions: Attache 294-6002' 30 mins. Casing to ted this wellbore a Abo formation. The to complete our che will require in the complete our check the check the check the check the complete our check the check t	and has corrent values of	determined on to retain to retain orkover pro	n ogram al to	
13. Describe proof starting are or recompleted. TD: 6357' 10.15.03: I hereby certify that	PED: 603 Load and to by Gerry 6 BP America that these TA status and developrovide for the information of the Kellie D	est carry, Na Process	SEE RULE 1 CIBP: 5982. Casing to 55 MOCD. Char Chection Componeduction perefore requirements of the control	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and ge Completions: Attache 294-6002' 30 mins. Casing to ted this wellbore a Abo formation. The to complete our che will require in the complete our check the check the check the check the complete our check the check t	and has corrent values of	determined on to retain to retain orkover pro	n ogram al to	-
13. Describe proof starting are or recompleted. TD: 6357' 10.15.03: I hereby certify that SIGNATURE Type or print name (This space for Starting are or star	PED: 603 Load and to by Gerry 6 BP America that these TA status and developrovide for the information of the Kellie D	est carry, Na Process	SEE RULE 1 CIBP: 5982. Casing to 55 MOCD. Char Chection Componeduction perefore requirements of the control	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and ge Completions: Attache 2994-6002' 30 mins. Casing to ted this wellbore a Abo formation. The complete our ch will require in the complete our character will be a second or	and has corrent values of	determined on to retain to	posed completion ogram al to TE 10.24.03 No. 505.394.164	-
13. Describe proof starting are or recompleted. TD: 6357 10.15.03: I hereby certify that SIGNATURE Type or print name	PED: 603 Load and to by Gerry 6 BP America that these TA status and developrovide for the information of the information of the use)	est carry, Na Process	SEE RULE 1 CIBP: 5982. Casing to 55 MOCD. Char Chection Componeduction perefore requirements of the control	103. For M 79' PERF: 0# psi. 1 t attached any has enotential: uested in er program	ultiple S: 5 Held d. valua in the orde n whi	pertinent details, and ge Completions: Attache 294-6002' 30 mins. Casing to ted this wellbore a Abo formation. The to complete our che will require in the complete our check the check the check the check the complete our check the check t	and has corrent values of	determined on to retain to	n ogram al to	-

