Form 3160-5 (August 2007)



UNITED STATES DEPARTMENT OF THE INTERIOR

NOV 1 0 2008

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT N.M. DIV-Dist. 25. Lease Serial No. 2 NM - 54400 SUNDRY NOTICES AND REPORTS ON WELLS Tand Avenue or Tribe Name

Do not use this form for proposals to drill onto re-enterial 88210

abandoned well. Use Form 3160-3 (APD) for such proposals.					0		
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas Well Other SWD				8. Well Name and No. Shell 15 Federal #23			
Name of Operator Nadel and Gussman Permain L.L.C.					9. API Well No. 30-005-62656		
3a. Address 601 North Marienfeld, Suite 508, Midland Tx 79701		3b. Phone No.	o. Phone No. (include area code)		10. Field and Pool or Exploratory Area		
432-682-4429)		Lucky Lake Queen		
4, Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1885 FNL, 660 FWL Unit E Sec 15 T15S R29E					11. Country or Parish, State Chaves Co. NM		
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO IND	ICATE NATURE	OF NOTIC	E, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Acidize Alter Casing	Deep	en ıre Treat		uction (Start/Resume) amation	Water Shut-Off Well Integrity	
Subsequent Report Final Abandonment Notice	Casing Repair	_	Construction		mplete	Other	
	Change Plans Convert to Injection	Plug	and Abandon		oorarily Abandon τ Disposal		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. It he proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 9/24/08 MIRU MAYO Marss Casing Pulling. ND wh and nu bop. RIH wi MMCPI tbg to 1727. Circ plugging mud. 9/25/08 ND bop weld on pull nipple. Surf pipe parted. RIH and cut csg @ 951'. Cut off surf csg. POH w 5-1/2" csg. 9/26/08 RIH and tag up @ 987'. Call BLM - ok. Pumped 40 sxs @ 987. POH WOC. TiH and tag @ 826'. PU to 362' and spot 50 sxs. TOH 9/30/08 TIH and tag @ 290'. Spot 25 sxs per BLM. PU spot 20 sxs from 60' to surf. Circ 35 sxs to surf. RD do wh and cot off wh. Cut off anchors. Clean and level location. ACCEPTED FOR RECORD APPROVED AS TO PLUGGING OF TMS WELL BORE. LABILITY LABORS WELL BORE. LABILITY LA							
Kem E. McCready	,		Title NM Operations Manager				
Signature Hom F. In Greed Date 10/27/2008							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by /S/ DAVI		OLEUM	ENGINEER	OCT 3 0 2008			
Conditions of approval, if any, are attached that the applicant holds legal or equitable t							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

entitle the applicant to conduct operations thereon.