Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA IAN 27 2009

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996



Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						LC-028784-B 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.				
SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well Other Other						9 \\(\(\) \(\)	Name and Na			
Oil Well X Gas Well Other						8. Well Name and No. Keely 26 Federal No. 1				
2. Name of Operator Cimarex Energy Co. of Colorado						9 API Well No.				
3a. Address			3b. Phone No. (include area code)			30-015-35025				
	PO Box 140907; Irving, TX 75014-0907	972	972-401-3111			10. Field and Pool, or Exploratory Area				
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description)					Loco Hills; Wolfcamp, NE				
	1980 FNL & 1550 FEL 26-17S-29E					11. County or Parish, State Eddy County, NM				
	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
	TYPE OF SUBMISSION TYPE OF ACTIO						N			
	Notice of Intent Acidize Alter Casing X Subsequent Report Casing Repair	Alter Casing Fracture Treat Reclar				Resume)	Water Shut-Of Well Integrity X Other Add			
		=	New Construction Recomplete Plug and Abandon Temporarily Aba							
	Final Abandonment Notice Convert to Injection		Plug Back Water Disposal				Tondamp perio			
13	Final Abandonment Notice Convert to Injection Plug Back Water Disposal 3. Describe Proposed or Completed Operation (clearly state all pertinent details, included estimated starting date of any proposed work and approximate duration thereof									
	If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 10.14.08 Killed well w/ 38 bbl 2% KCL water. NU BOP and TOOH w/ tubing. 10.15.08 Set CBP @ 9174.' Perfed Wolfcamp 9102' - 9161' (9151-61' and 9118-21' and 9106-16' and 9102-06') 93 holes, 3 spf, 120° phasing.									
	Dumped 1 sx sand on top of CBP @ 9174.' 10.17.08 Acidized 9102' - 9161' w/ 883 bbls Deepspot 15% HCl acid, gelled 15% HCL, slick water, and 450 ball sealers. 10.21.08 Installed 2%" tubing to 9147' w/ TAC @ 8986' and SN @ 9117.' 10.22.08 Installed rod pump system - 2½" x 1½" x 24' RHBM. 10.26.08 Turned well back to sales as Loco Hills; Wolfcamp, NE gas well. New well test: 24 hrs, gas 70 mcf, oil 3 bbls, water 112 bbls, csg pressure 40, tbg pressure 200, choke 20/64. ACCEPTED FOR RECORD									
14	I hereby certify that the foregoing is true and correct		1		_					
Name (Printed/Typed) Natalie Krueger Signature Gerry Guye, Deputy Fie NMOCD-District II			19 Regulatory Analyst AC(CEPTED FOR RECORD				
			FSI Ary 8, 2009			.14.N	2 4 2009			
_	THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by				Title		400	no Dare]		
	anditions of Approval, if any, are attached. Approval of this notice does in the applicant holds legal or equitable title to those rights in the spirit would patitle the applicant to conduct programme.			Office		CARLSBA	AND MANAGEM D FIELD OFFICE	ENT		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or

fraudulent statements or representations as to any matter within its jurisdiction.