Submit 3 Copies To Appropriate District	C4-4 CNI M	·	FEB 1 7 2009	F C 102
Office	State of New Mo Energy, Minerals and Nati	•		Form C-103 June 19, 2008
District I 1625 N French Dr., Hobbs, NM 88240	Energy, winterars and react	urar resources	WELL API NO.	-011070
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	1-04038
District III 1000 Rio Brazos Rd, Aztec, NM 87410	1220 South St. Francis Dr.		, , , , , , , , , , , , , , , , , , ,	EE 🗌
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease 1	No.
1220 S St Francis Dr., Santa Fe, NM 87505				EASE NMNM2747
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA	CES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PL		7. Lease Name or Unit Ag	greement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			JACKSON B  8. Well Number #15	
1. Type of Well: Oil Well Gas Well Other M/R / N			#13	
2. Name of Operator BURNETT OIL CO., INC			9. OGRID Number '003080	
3. Address of Operator 801 CHERRY STREET, STE 1500, UNIT #9, FORT WORTH, TEXAS 76102			10. Pool name or Wildcat SQUARE LAKE (GB-SA)	
4. Well Location				
Unit Letter L: 1980' feet from the SOUTH line and 660' feet from the WEST line				
Section 1 Township 17S Range 30E NMPM County EDDY  11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
The second secon	3707'			
12 Check A	ppropriate Box to Indicate N	Nature of Notice	Report or Other Data	
			•	05
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK □ PLUG AND ABANDON 🕱 REMEDIAL WORK □ ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	т јов □	
,		OTHER.	•	"
OTHER:  13. Describe proposed or complete.	eted operations. (Clearly state all	OTHER:	d give pertinent dates, includ	ling estimated date
of starting any proposed wor recompletion.	rk). SEE RULE 1103. For Multij	ple Completions: At ED 1/1945	tach wellbore diagram of pro	oposed completion
PRESENT WELL CONDITION: 8-1/4" CSG @ 558' W/50 SKS CMT, 5-1/2" CSG @ 2838' W/100 SKS CMT. O/H TD IS 3161'.				
P&A PRODECURE AS FOLLOWS: 9.5 PPG BRINE WATER W/MUD GEL WILL BE CIRCULATED BETWEEN EACH PLUG.  1.) Notify BLM-Carlsbad and NMOCD- Artesia before work begins. 2.) RUSU, NU BOP.3.) Pull & LD cmt lined tbg & packer.				
4.) GIH w/2-7/8' workstring w/ bit w/5-1/2" csg scraper, run to 2730'.( DO NOT RUN INTO OH.) POOH W/ ALL.				
5.) GIH w/ Cement retainer & set @ 2650'. Pump 50 sks cement to cover top of San Andres (2711') and producing interval.				
6.) Pull out of retainer and POOH w/workstring. 7.)Perforate 4 squeeze holes @ 1450' (50' below Top of Yates and Base of Salt at 1399'.) 8.) GIH w/workstring and packer, pump 50 sks inside & outside of casing above & below Base of Salt @ 1399'.				
WOC. TAG PLUG. 9.) Perforate 4 squeeze holes @ 610' ( to be 50' below base of 81/4" surface csg shoe.)				
10.) RIH w/packer and pump 50 sks cement through squeeze holes to obtain 50' cement plug inside & outside 5-1/2" casing				
above and below 8-1/4" casing shoe @ 558' and Top of Salt @ 413'. WOC. TAG PLUG. 11.) Perforate 4 squeeze holes @ 60'. Pump 25 sks cement through squeeze holes to circulate to surface.				
NOTE: All cement plugs, including 10% for each 1000' of de	uding surface plugs, should l	eave 25 sk minim	um inside casing and be	at least 100',
Spud Date off csg and wellhead		L.13.) RDSU.		
14.) Install P&A marker. RES	TORE LOCATION FOR FINAL	BLMINSPECTION	N.	
14.) Install P&A marker. RES	TORE LOCATION FOR FINAL	. BLM INSPECTIO	N	
I hereby certify that the information a	bove is true and complete to the l	best of my knowledg	ge and belief.	
SIGNATURE Markai	TITLE EN	GINEERING MANA	GER DATE N	1 /09/2009
140 514		· · · ·		(217) 222 5122
Type or print nameMARK A.  For State Use Only	JACOBY E-mail addres	SS:	PHONE:	(817) 332-5108
APPROVED BY:	TITLE		DATE	
Conditions of Approval (if any):	Accepted for reco	ra —	,	
	·			, / ,
				. MY