Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.
District II	OIL CONSERVATION DIVISION		30-105-20829
811 South First, Artesia, NM 88210 District III	2040 South Pacheco		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	ztec, NM 87410 Santa Fe, NM 87505		STATE X FEE
District IV 2040 South Pacheco, Santa Fe, NM 87505		6. State Oil & Gas Lease No. K-6290	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PEUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM CADI) FOR SUCH			7. Lease Name or Unit Agreement Name:
PROPOSALS)			AIRPORT GRACE
1. Type of Well: Oil Well Gas Well	☑ Other	JED 2 55	
2. Name of Operator	(D)	Son Aller	8. Well No.
Lynx Petroleum Cor	nsultants, Ind?	APTED 23	1
3. Address of Operator P.O. Box 1708, Hol	\&	15/4 E	9. Pool name or Wildcat CARLSBAD, CANYON, SOUTH
4. Well Location			
Unit Letter K: 1980 feet from the South line and 2164 feet from the West line			
Section 36		ange 26E	NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3221' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB	ND
OTHER:		OTHER: RECO	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.			
9/8/03: PLUG BACK AS FOLLOWS:			
1. NU BOPE. Pulled packer and tubing.			
2. Set 7" C.I.B.P. at 10395' and dumped 35' cement on top.			
3. Perforate Canyon 10200'-05' w/4jspf. Ran tubing and packer to 10133' and swabbed well dry with no show.			
4. Set 7" C.I.B.P. at 10160' and dumped 35' cement on top.			
5. Perforated Canyon 9862'-66' w/4jspf. Ran tubing and packer to 9790' and swabbed well dry with slight gas show.			
6. Acidized with 1000 gals 15% HCL. Swabbed back load. Put well on test.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Man	CUL TITLE	President	DATE 9/22/03
Type or print name Maric Wi	se		Telephone No. 505-392-6950
(This space for State uses)	ORIGINAL SIGNED BY TIM W	. Gum	SEP 2 7 2003
APPPROVED BY Conditions of approval, if any:	DISTRICT II SUPERVISORLE		DATE