Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No. NM-100558 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. RDX 15-1 Oil Well Gas Well Other 9. API Well No. 30-015-35955 2 Name of Operator RKI EXPLORATION & PRODUCTION, LLC 10. Field and Pool or Exploratory Area 3a. Address 3b. Phone No (include area code) 3817 NW EXPRESSWAY, SUITE 950 OKLAHOMA CITY, OK 73112 **BRUSHY DRAW DELAWARE EAST** 405-949-2221 4. Location of Well (Footage, Sec., T.,R,M, or Survey Description) 330 FNL, 330 FNL, SEC. 15, T-265, R-30E 11 Country or Parish, State EDDY COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Acidize Deepen Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other ✓ Subsequent Report Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) RKI EXPLORATION & PRODUCTION, LLC REQUESTS PERMISSION TO DISPOSE OF PRODUCED WATER VIA A 3" POLY LINE TO THE CRW DISPOSAL SYSTEM. THE CRW SWD NM-55685 ROSS DRAW COM #1 IS LOCATED AT THE NE/NW 1/4 OF SEC. 33, T-26S, R-30F IN EDDY COLINTY, NA ACCEPTED FOR RECORD THIS WELL PRODUCES BETWEEN 80 - 100 BBLS OF WATER PER DAY. APR 1 3 2009 **lecepted for record** /s/ JD Whitlock Jr BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) GENE SIMER Title PRODUCTION SUPERINTENDENT Date 03/30/2009 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would