Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 Revised March 25, 1999	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-015-22597	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE X FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama re, 1414 67303		6. State Oil &	Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other			7. Lease Name or Unit Agreement Name: EMPIRE ABO UNIT "H"	
2. Name of Operator	RECEIVED		8. Well No. 281	
BP AMERICA	DEC 1 7 2003		O Della Willed	
3. Address of Operator			9. Pool name or Wildcat EMPIRE ABO	
P.O. BOX 1089 Eunice, NM 88231 4. Well Location	OCD-ARTESIA EMPIRE ABO		ВО	
Unit Letter P : 200 feet from the SOUTH line and 660 feet from the EAST line				
Section 32	Township 17S	Range 28E		M EDDY County
	10. Elevation (Show whether Dl 3674' KB	R, RKB, RT, GR, et	c.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK X	PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A	ND	
OTHER:		OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
TD: 6300' PB: 6310' CSG: 5 ½" - 15.5# PERFS: 6119'-6252'				
1. MIRU PU POOH W/ RODS AND PUMP				
2. ND WH NU BOP POOH W/ TBG				
3. RU WIRELINE TO RUN TDT LOGS ACROSS ABO REEF 4. PERFORATE ABO REEF OFF OF TDT LOGS				
5. RIH W/ PKR SPOT 15% HCL ACROSS PERFS SET PKR				
6. ACIDIZE W/ 15% HCL 50 GAL PER FT OF PERFS				
7. RIH W/ PRODUCTION TBG BELOW BOTTOM PERF ND BOP NU WH				
8. SWAB TEST WELL TO CLEAN UP				
9. RIH W/ PUMP AND RODS 10. RTP	•			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Juif	TTTLE_Well Te	am Lead	DATE	_12/3/2003
Type or printingine Jim Pierce	Telephone No. 505-677-3642			
(This space for State 19 2003) W. Sum SUPERVISOR, DISTRICT II DEC 1 9 2003				
APPPROVED BY	TITLE	SUFFICE	.,	DATE 1 3 ZUUS