KW

Submit One Copy To Appropriate District Office State of New Mex	
District   Energy, Minerals and Natur 1625 N French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave., Artesia, NM 88210 OIL CONSERVATION	DIVISION 30-005-62172 5 Indicate Type of Leave
District III 1220 South St. Fran	cis Dr.  5. Indicate Type of Lease  STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 (PRICE 1000 Rio Brazos Rd., Aztec, Az	505 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	0. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	
PROPOSALS)	8. Well Number 9
1. Type of Well: Oil Well Gas Well X Other P&A	
2. Name of Operator	9. OGRID Number
Texas ReExploration Operating LLC	
3. Address of Operator	10. Pool name or Wildcat
1750 Seamist Drive Suite 170 Houston TX 77008	RaceTrack San Andres
4. Well Location	
Unit Letter D: 990 feet from the North line and 990 feet from the West line	
Section 29 Township 10S Range 28E NMPM County Chaves	
11. Elevation (Show whether DR, 3735)	RKB, RT, GR, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE COMPL	CASING/CEMENT JOB
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
☐ If this is a one-well lease or last remaining well on lease, the battery	and pit location(s) have been remediated in compliance with
OCD rules and the terms of the Operator's pit permit and closure plan.	All flow lines, production equipment and junk have been removed
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)  All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
	6 71 10
SIGNATURE TITLE	President DATE 6-24. OC
TYPE OR PRINT NAME Robert K. Hillin Sr E-MAIL: For State Use Only	
ARREQUED BY: A HALL . THE STATE OF THE STATE	1 Del DATE 2/2/200