## UNITEDSTATES DEPARTMENT OF THE INTERIOR

OCD-A	RTESIA
-------	--------

FORMAPPROVED OM B No 1004-0137 Expires March 31, 2007

RM
$V_{\rm in}$

BUREAU OF LAND MANAGEMENT 5. Lease Serial No. ∂**ÑM**NM90807 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1 Type of Well X Oil Well Gas Well Other 8. Well Name and No Osage Federal Battery 2. Name of Operator 9. API Well No. St. Mary Land & Exploration Co. 30-015-<del>2008</del>9 26 28 3 3a. Address 3b. Phone No. (include area code) 3300 N. A Street, Bldg. 7, Ste. 200 Midland, TX 7970832)688-1789 10 Field and Pool, or Exploratory Area Parkway: Bone Springs 4. Location of Well (Footage, Sec., T, R, M., or Survey Description) 11. County or Parish, State 1980' FNL & 1980' FEL, Sec. 34, T-19-S, R-29-E UL:G Eddy County, NM SW 4/NE 4 12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPEOF ACTION ☐ Acidize Deepen 🗌 Production (Start/Resume) ☐ Water Shut-Off Notice of Intent AlterCasing ☐ FractureTreat Reclamation Well Integrity OtherFlare due to New Construction Recomplete X Subsequent Report Change Plans Compressor down Plug and Abandon \_] Temporarily Abandon Convert to Injection PlugBack Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) St. Mary Land & Exploration experienced compressor down time at our Osage Battery on 6/22/09. Gas flared for approx 5 hours. Estimated gas flared was 59 mcf. ACCEPTED FOR RECORD Wells that flow through pipeline are: Csage Federal #008 30-015-26089 Osage Federal #009 30-015-26157 Osage Federal #010 30-015-26178 JUL 2 7 2009 Osage Federal #013 30-015-26216 /s/ JD Whitlock Jr Osage Federal #015 30-015-26271 Osage Federal #016/30=015-26283---BUREAU OF LAND MANAGEMENT SEE ATTACHED FOR CARLSBAD FIELD OFFICE CONDITIONS OF APPROVAL 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Donna Huddleston Title **Production Tech** Signature 06/24/2009 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

## **Osage Federal Battery**

## St. Mary Land & Exploration Co

July 27, 2009

## **Condition of Approval to Flare Gas**

- 1. Report all volumes on MMS OGOR reports.
- 2. Comply with NTL-4A requirements
- 3. Subject to like approval from NMOCD
- 4. Flared/vented volumes will still require payment of royalties
- 5. Install gas meter on vent/flare line to measure gas prior to venting/flaring operations if it is not equipped as such at this time.