		GED I & COUS	
	Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103	
	<u>District I</u> Energy, Minerals and Natural Resources	June 19, 2008	
	1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-015-21899	
	District III OIL CONSERVATION DIVISION 1220 South St. Francis Dr	5. Indicate Type of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Fe NM 87505	STATE FEE S	
	District IV 1220 S. St. Francis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.	
87505		7. Lease Name or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	McCaw BT	
	DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number	
l	1. Type of Well: Oil Well Gas Well Other	5	
ļ	2. Name of Operator	9. OGRID Number	
1	Yates Petroleum Corporation	025575	
	3. Address of Operator105 South Fourth Street, Artesia, NM 88210	10. Pool name or Wildcat Eagle Creek SA	
-	4. Well Location	Lagie Cleek SA	
	Unit Letter A: 380 feet from the North line and	940 feet from the East line	
	Section 14 Township 17S Range 25E	NMPM Eddy County	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	3495'GR		
12. Cheek Ammanista Day to Indicate Natura of Nation Demont on Other Date			
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
		UBSEQUENT REPORT OF:	
	PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL W		
	TEMPORARILY ABANDON	DRILLING OPNS.☐ P AND A ☐ MENT.IOR ☐	
	DOWNHOLE COMMINGLE		
	OTHER:	П	
-	OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details	s, and give pertinent dates, including estimated date	
	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
	or recompletion.		
Yates Petroleum Corporation plans to plug and abandon this well as follows:			
 MIRU all safety equipment as needed. NU BOP. Set a 4-1/2" CIBP at 1322' and cap with 35' cement. 			
3. Circulate hole with salt gel mud. Spot 25 sx cement plug across the intermediate casing shoe from 1165'-1265'. WOC and tag plug,			
reset if necessary.			
4. Spot 25 sx cement plug across the surface casing shoe from 284'-384'. WOC and tag plug, reset if necessary.5. Spot 25 sx surface plug from 0-100'. WOC and tag plug, reset if necessary.			
6. Cut off wellhand and install dry halo marker and alon location as nor regulated			
	Notify OCD 24 hrs. prior		
	NOTE: Yates Petroleum Corporation will use steel pits and no earth pits To any work done.		
		;	
	Could Date:		
	Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Regulatory Compliance Supervisor DATE September 17, 2009			
	Type or print name <u>Tina Huerta</u> E-mail address: <u>tinah@yatespetroleu</u>	<u>ım.com</u> PHONE: <u>575-748-4168</u>	
	For State Use Only	. ,	
APPROVED BY: TITLE Approval Granted providing work DATE 9/21/09			
Conditions of Approval (if any): is complete by 12/21/09			
	.	•	



