Submit 1 Copy To Appropriate District	0	
Office	State of New Mexico	Form C-103
District I Ener	gy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II	CONGERNATION DEMONS	WELL API NO30-015-20172
1301 W. Grand Ave., Artesia, NM 88210 OII District III	CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV 1220 S. St. Francis Dr , Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND	DEDODTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DR DIFFERENT RESERVOIR. USE "APPLICATION FOR	LILL OR TO DEEPEN OR PLUG BACK TO A	Gulf
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well	Other RECEIVED	8. Well Number 1
2. Name of Operator	OCT 1 9 2009	9. OGRID Number 020451
Momentum Operating Co., Inc. 3. Address of Operator	001 10 2500	10. Pool name or Wildcat SHUGART
P O Box 2439, Albany, TX 76430	NMOCD ARTESIA	Y-SR-OU-GB
4. Well Location		
	tet from the _ NORTH_ line and330	feet from the _EASTline
Section 28	Township 18S Range 31E ation (Show whether DR, RKB, RT, GR, etc.	NMPM EDDY County
3634	· ·	
12. Check Approprie	ate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTIO	NITO: SUR	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
<u></u>	LE COMPL CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE		,
OTHER:	☐ OTHER:	· <u> </u>
13. Describe proposed or completed opera of starting any proposed work). SEE 1	tions. (Clearly state all pertinent details, and RULE 19.15.7.14 NMAC. For Multiple Co.	d give pertinent eletes, including estimated date mpletions: Attackerellbore diagram of
proposed completion or recompletion.	•	6000
1. Set 5 ½" CIBP @ 3200' W/35' Ceme	nt on top. Circulate well with PXA mud.	My 20
2. Perforate and attempt to squeeze a 40	sack cement plug @ 1995-1895.	asing shoe and surface plug)
3. Perforate and attempt to squeeze to sur	rface a 100 sack cement plug 870-0 (8 5/8 c	asing shoe and surface plug)
4. Dig out and cut off well head 3' B.G.I	.; weld on steel plate and dry hole marker.	
3	,	
	Approval Gr	ented providing work
	is complete	by 12/29/07
	·	′ /
Spud Date: 11–15–09	11-20	0-09
I hereby certify that the information above is tr	ue and complete to the best of my knowledg	ge and belief.
SIGNATURE	TITLETreasurer	DATE10-15-09
Type or print name Lynn Neff	E-mail address: nefflynn@aol.com	n PHONE: 325762-3331
For State Use Only		
		· / / / -
APPROVED BY:	TITLE	DATE 10/27/09

Top Salt @ 800 85,8 24#@827.10" Hove cement-w/505x Base of Salt@ 1945 Perf. + attempt squeeze to surface 870'-0' casing shoe + surface plug. 100 sx Perf. + attempt squeeze 40 SX Cement plus 1995-1895 (Base of Sail) Wait on cement & tas top of cement Circulate well wi mud Top of cement 2700 (caid) Set CIBP @ 32001 W/35 ement on top Pump 125 SX, unstins & pump 25 SX above retainer Penrose Perfs. 3524-3558 Grayburg Perfs 3800-3915 572" 14# @ 3927' cemented W/150 sx 3" hole. Top of cement @ 2700 (calc)