Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

and bearing to the end of Africa.

STATES
FORM APPROVED
OMB NO. 1004-0135
D MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires. July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 5. Lease Serial No. NMLC029419B

abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee of	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRI	7. If Unit or CA/Agre NMNM71030A	7. If Unit or CA/Agreement, Name and/or No NMNM71030A			
T Type of Well				8. Well Name and No.	
Oil Well Gas Well GOther: INJECTION			SKELLY UNIT 84	1	
Name of Operator FOREST OIL CORPORATION	LY HARRIS toil.com	9. API Well No. 30-015-05423-	9. API Well No. 30-015-05423-00-S1		
3a. Address 707 17TH STREET SUITE 36 DENVER, CO 80202	Phone No. (include area code : 303-812-1676 : 303-864-6105) 10 Field and Pool, or GRAYBURG	10 Field and Pool, or Exploratory GRAYBURG		
4. Location of Well (Footage, Sec., 7	1 HECEIVE	11. County or Parish, and State			
Sec 27 T17S R31E NENE 660	DEC 31 200	9 EDDY COUNT	EDDY COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	DLYMPGPLABJE	SOAICE, REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	PE OF SUBMISSION TYPE OF ACTION				
Nederseller	☐ Acidize	Deepen	Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	☐ Alter Casing	Fracture Treat	Reclamation	Well Integrity	
☐ Subsequent Report	Casing Repair	☐ New Construction	Recomplete	Other	
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon		
•	☐ Convert to Injection	□ Plug Back	☐ Water Disposal	Į.	
Forest Oil Corporation respect recomplete the Skelly 84 to the a CIBP at 3299', set on 3/20/04/2/2010. SUBJECT TO LIKE APPROVAL BY STATE	tfully requests TA approval so e Seven Rivers and return the or. The last MIT was 5/19/200 SEE ATTACH CONDITIONS	e well to production. This 09. The OCD approved	s injector has TA status until		
lastused as wil					
14. I hereby certify that the foregoing is	Electronic Submission #776	ORPORATION, sent to th	e Carlsbad		
Name (Printed/Typed) KELLY HA	· ·	• •	LATORY TECH		
Signature (Electronic	Submission)	Date 11/17/2	2009		
<u> </u>	THIS SPACE FOR I	FEDERAL OR STATE	OFFICE USE		
Approved By DUNCAN WHITLOCK		TitleLEAD PE	TROLEUM ENGINEERING TEC	CH Date 12/26/20	
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to conditions.	warrant or ject lease Office Carlsba	ad			
Title 18 U.S.C Section 1001 and Title 43	U.S.C. Section 1212, make it a crin	ne for any person knowingly ar	nd willfully to make to any department	or agency of the United	

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Skelly Unit #84. Well may be approved to be TA/SI for a period of 4 months until 4/2/10 after successful MIT and subsequent report is submitted. This will be the last and only TA/SI approval. Well must be P&A or plans to use well must be submitted by 4/2/10. IF well is going to be used as a WIW cement behind Production string needs to be circulated to surface. No bleed off is allowed on WIW MIT