

District I - (505) 344-6161
P.O. Box 1880
Hobbs, NM 88241-1880
District II - (505) 746-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6175
1000 Rio Grande Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Mineral and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131



Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

30-015-30902

Release Notification and Corrective Action

OPERATOR

☒ Initial Report☐ Final Report

Name PECOS PRODUCTION COMPANY	Contact Ralph Skinner Jr.
Address 400 W. ILLINOIS SUITE 1070	Telephone No. 432-664-5194
Facility Name BATSH FEDERAL No. 6	Facility Type Well/Location Site

Surface Owner	Mineral Owner	Lease No. LC-029389-A
---------------	---------------	---------------------------------

LOCATION OF RELEASE

Unit Letter E	Section 9	Township 18S	Range 31E	Feet from the 1980	North/South Line FNL	Feet from the 660	East/West Line FWL	County EDDY
-------------------------	---------------------	------------------------	---------------------	------------------------------	--------------------------------	-----------------------------	------------------------------	-----------------------

NATURE OF RELEASE

Type of Release Straw oil	Volume of Release 20 bbls	Volume Recovered 0
Source of Release Tank/Daluc leak on location	Date and Hour of Occurrence 12/31/03 8:00 am	Date and Hour of Discovery 12/31/03 9:30 am
Was immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? 15ccil (BLM) Duncan Whitlock 2nd (BCD) message to Gary Wink	
By Whom? Ralph Skinner Jr.	Date and Hour 12/31/03 (BLM) @ 10:30 am 1/1/04 (BCD) @ 11:00 am	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a watercourse was impacted, Describe Fully. (Attach Additional Sheets if Necessary)

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary)

Test tank leaking due to cracked Daluc or hole in bottom on location.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets if Necessary)

Area affected was on location (caliche pad) and 6'-10' off edge of pad (Sandy)
Tank was emptied, picked up & cleaned beneath tank. Pit liner was laid on pad.
Everything off pad was picked up by backhoe & put on liner & remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation all operators are required to report and/or the certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Ralph Skinner Jr.	OIL CONSERVATION DIVISION	
Printed Name: Ralph Skinner Jr.	Approved by District Supervisor:	
Title: Production Supervisor	Approval Date:	Expiration Date:
Date: 1-2-04	Phone: Tom Carreras 432-620-8480 (of Pica)	Conditions of Approval:
E-mail: Beabop1 Sandy@aol.com 432-664-5194 (cell)		Attached ☐

Ralph Skinner. 432-664-5194.